

December 12, 2007

Mr. Burt Presnell
Principal Real Property Agent
County of Riverside Department of Facilities Management
3133 Mission Inn Avenue
Riverside, California 92507-4138

SUBJECT:

Phase II Environmental Site Assessment Report

Potential County Fire Station Purchase (County #030-EO)

Al's Corner Project Site

7010 Hamner Road - APN 152-050-003

Corona, California EEI Project No. 70413

Dear Mr. Presnell,

EEI has completed the following *Phase II Environmental Site Assessment Report* for the above referenced subject property (**Figure 1**). The following report presents a purpose and objective, brief background information, geology and hydrogeology, field investigation, laboratory, and a discussion of findings, conclusions, and our recommendations.

PURPOSE AND OBJECTIVE

The purpose of this *Phase II Environmental Site Assessment* was to investigate environmental conditions noted during our Phase I Environmental Site Assessment (EEI, 2007) previously conducted at the project site. Environmental conditions observed included stained soils from vehicle usage; 55-gallon capacity storage drums; miscellaneous containers containing what appeared to be waste oil; and two (2) potential historical underground storage tanks (USTs). It has been noted by County of Riverside officials, that historical retail fuel services may have been provided onsite.

The objective of this *Phase II Environmental Site Assessment* was to, 1) determine through a geophysical investigation if USTs, or if evidence of former UST tank pit cavities were present, and 2) conduct soil and groundwater (if encountered) sampling throughout the project site to determine if any chemicals of concern have been released to the subsurface. Chemicals of concern would consist of (but are not limited to) petroleum hydrocarbon constituents, heavy metals and volatile organic compounds (VOCs).

BRIEF PROJECT SITE BACKGROUND

The subject property is located at 7010 Hamner Avenue in the City of Corona, Riverside County, California (Figure 1). Schleisman Road is located to the north, undeveloped land to the south, Hamner Avenue and residential development beyond to the east and residential tracts to the west (Figure 2). The subject property is comprised of approximately 1.6 acres of developed land. Site structures include a bar/restaurant building (Al's Corner); a residential structure; and a barn storage area with two connected storage units on each side. The rest of the property is covered with several stored vehicles, unidentified drums, septic tank vents, minor debris and a water well.

GEOLOGY AND HYDROGEOLOGY

The subject property lies within the Peninsular Ranges geomorphic province. The Peninsular Ranges geomorphic province, one of the largest geomorphic units in western North America, extends from the Transverse Ranges geomorphic province and the Los Angeles Basin, south to Baja California. It is bound on the west by the Pacific Ocean, on the south by the Gulf of California and on the east by the Colorado Desert Province. The Peninsular Ranges are essentially a series of northeast-southeast oriented fault blocks (CGS, 2002). The regional geologic map of the Corona North 7.5-minute Quadrangle (Morton & Gray, 1995) indicates the subject property is underlain by early Pleistocene-age "very old alluvial channel deposits," designated on the map as Qvoa. According to Morton & Gray, these deposits consist of reddish-brown, gravel, sand, and silt which are well-indurated with well-dissected surfaces. This unit underlies a large area between the Santa Ana River and Temescal Wash (Morton & Gray, 1995).

Three major faults zones and some subordinate fault zones are found in this province. The Elsinore Fault zone and the San Jacinto Fault zones trend northwest-southeast, and are found near the middle of the province. The San Andreas Fault zone borders the northeasterly margin of the province, whereas, a fault related to the San Andreas Transform Fault System, the Newport-Inglewood - Rose Canyon Fault zone, exists near the western margin and Continental Borderland geomorphic province.

Soil in the vicinity of the site has been identified by USDA (1974) as Hanford Series at two (2) to eight (8) percent slopes. Soils within the Hanford Series are gently to moderately sloping soils occurring on alluvial fans. The Hanford Series consists of well-drained soil.

According to the California Regional Water Quality Control Board – Santa Ana Region (8) (CRWQCB, 1995), the subject site is located within the Temescal Groundwater Sub-Basin of the Upper Santa Ana River Basin. Groundwater in this subarea has been designated as beneficial for municipal and agricultural use, industrial service supply and process.

FIELD ASSESSMENT

Geophysical Investigation

On November 19 and 21, 2007, a geophysical survey was conducted by SubSurface Surveys. An EEI representative was onsite to observe the investigation. The purpose of the geophysical investigation was to identify any anomalies that would suggest or indicate the presence of a UST, tank pit area, underground piping, or buried debris which may have existed from historical fuel service activities or site use.

A combination of ground penetrating radar (GPR), electromagnetic induction (EM), and line tracing was utilized. Recording parameters, such as lines per inch, chart speed, and gain are "tuned" to the subsurface by a series of traverses designed to calibrate the instrument. An approximately 500 megahertz signal, is transmitted throughout the subsurface, which reflects materials in direct proportion to their conductivity and impedance (the product of velocity and density). Highly conductive soils, such as clay, reflect much of the original signal. When soils of differing conductance are encountered, the signal is diffracted at an angle to its incidence, thus resulting in diffraction." A UST or an excavation that is filled with backfill with debris will have different conductivity then undisturbed "native" soil. The UST or edges of excavations will often cause diffractions as well.

During the investigation, two (2) anomalies, located along the east and west side of Al's Corner building, were detected. Based on SubSurface Survey's interpretation of the field data, the anomaly to the east of the building appears to be a former UST, while the anomaly to the west of the building appears to be a septic tank.

The complete geophysical investigation report, prepared by SubSurface Surveys is provided as **Appendix A**. The approximate location of the identified anomalies is illustrated in **Figure 2**.

Soil Investigation

Soil sampling was conducted to further investigate observed environmental conditions noted in our Phase I ESA (i.e., stained soils and hazardous waste storage areas), as well as the potential UST locations. Prior to mobilization, County of Riverside personnel were notified, and assisted with site access. Boring locations were "marked-out," and Underground Services Alert (USA) was notified for subsurface utility clearance (Ticket No. A73200459).

On November 19 through 21, 2007, EEI personnel mobilized to the project site to conduct soil and groundwater sampling. A combination of hand auger and direct push technology (DPT) was used to evaluate soil conditions for the presence of chemicals of concern (**Figure 2**).

Boring locations S1 through S7 are hand auger boring locations, used to evaluate near-surface soils (6 to 18 inches below grade) in the areas of stained soils, next to 55-gallon storage drums, and used motor oil storage areas. Borings S1 through S4 are located on the northwest portion of the property, while borings S5 through S7 are located on the southwest portion of the property. Boring locations B1 through B7 are DPT boring locations, used to evaluate the potential UST and septic tank located east and west of Al's Corner building, as well as general storage areas. Borings B1, B6 and B7 were advanced adjacent to the UST location; boring B3 was advanced adjacent to the septic tank; and borings B2 and B5 were advanced along the southeast and southwest portion of the property, respectively. DPT borings were advanced to a maximum depth of 50 feet bgs. For DPT borings, soil samples were collected at 5-foot intervals.

Soils encountered during this investigation consisted of fine to medium grained sands. Physical evidence of contamination (i.e. petroleum hydrocarbon odor and/or staining) was observed at boring locations S2 through S4, and appeared to be from improper storage of used motor oil. Groundwater was not encountered; therefore, samples were not collected. **Appendix B** contains copies of boring logs.

Soil samples were collected in four (4)-ounce glass jars (hand auger borings) and acetate liners (DPT borings). After the sample was collected, the jar/liner was sealed with Teflon™ tape, plastic caps, custody sealed, and labeled with a number unique to the sample. Each sample was then placed in a chilled cooler for transport to SunStar Laboratories, Inc. in Tustin, California, under proper chain-of-custody (COC) documentation. Appendix C contains complete laboratory analytical results and COC documentation.

Organic vapor concentrations from soil samples were monitored by transferring a representative amount of sample material from the sample container into a Zip-lock™ bag; desegregating the sample; allowing hydrocarbons (if any) to volatilize; and measuring head space vapor with a MiniRae 2000™ photoionization detector (PID) sample probe. Prior to mobilization, the PID was decontaminated and properly calibrated to 100 parts per million (ppm) isobutylene.

Upon completion of each boring, sampling equipment was rinsed using an Alconox[™] detergent solution, followed by a double tap-water rinse. All borings were backfilled with bentonite chips, hydrated, and the ground surface was completed with an appropriate cap material.

LABORATORY ANALYTICAL PROGRAM

Soil samples submitted for laboratory analytical screening were analyzed for gasoline, diesel, and motor oil range carbon chain identification (CCID, C6-C40) by United States Environmental Protection Agency (USEPA) Test Method 8015M, Total Petroleum Hydrocarbons as Gasoline (TPH-G) and Volatile Organic Compounds (VOCs) by USEPA Test Method 8260B, and CAM 17 Metals and Total Lead by USEPA Test Method 6010B. Complete laboratory analytical reports with COC documentation are included in **Appendix C**.

QUALITY ASSURANCE/QUALITY CONTROL

For samples collected during this survey, the following QA/QC analysis was conducted by SunStar Laboratories:

- · Blank Sample
- Matrix Spike and Duplicate

These types of QA/QC checks are employed routinely by SunStar Laboratories, Inc. to ensure accurate data. The standard operating procedures for each analysis have specific types and frequency of QA/QC checks which are followed at a minimum. Laboratory QA/QC checks also include an evaluation of blanks, precision, accuracy and recovery.

EEI reviewed SunStar Laboratories' documentation for all samples submitted during this assessment to ensure that appropriate sample collection, extraction times, holding times, analysis and acceptable QA/QC limits were in compliance. All samples analyzed during the referenced reporting period were in compliance with the appropriate QA/QC standards employed by the laboratory.

LABORATORY ANALYTICAL RESULTS

The following section discusses laboratory analytical results for soil samples submitted for testing. The attached **Table 1** is a summary of laboratory analytical results. Complete laboratory analytical results and COC documentation are included as **Appendix C**.

Volatile Fuel Hydrocarbons

Gasoline Range Organics (GRO) (C6-C12): GRO was reported in samples collected from locations S5 and S7. Concentrations ranged from 7.3 milligrams per kilogram (mg/kg) (S5 at 0.5 feet bgs) to 27 mg/kg (S7 at 0.5 feet bgs). All other samples analyzed for GRO reported concentrations less than the laboratory reporting limit (0.10 mg/kg).

Diesel Range Organics (DRO) (C13-C28): DRO was reported in samples collected from locations S2 through S7. Concentrations ranged from 28 mg/kg (S4 at 0.5 feet bgs) to 2,200 mg/kg (S2 at 0.5 feet bgs). All other samples analyzed for DRO reported concentrations less than the laboratory reporting limit (0.10 mg/kg).

Motor Oil Range Organics (MORO) (C29-C40): MRO was reported in samples collected from locations S2 through S7. Concentrations ranged from 110 mg/kg (S4 at 0.5 feet bgs) to 20,000 mg/kg (S2 at 0.5 feet bgs). Note, location S2 was heavily stained by what appeared to be used motor oil. All other samples analyzed for MORO reported concentrations less than the laboratory reporting limit (0.10 mg/kg).

Volatile Organic Compounds (VOCs)

Soil samples submitted laboratory analytical testing of Benzene, Toluene, Ethylbenzene and Xylene (BTEX), and other Volatile Organic Compounds (VOCs) reported concentrations less than the laboratory reporting limit (5.0 to 500 micrograms per kilogram, $\mu g/kg$), except for sample S7 at 0.5 feet bgs. P-Isopropyltoluene was reported at 14 $\mu g/kg$. P-Isopropyltoluene is not a regulated constituent; therefore, based on the low concentration and isolated reported value, further environmental evaluation is not warranted at this time.

California Assessment Manual (CAM) 17 Metals

Samples collected and analyzed from locations S1 through S7, B2 and B5 were analyzed for CAM 17 Metals. Samples collected and analyzed from locations B1, B3, B4, B6 and B7 were analyzed for Total Lead. Concentrations of select CAM 17 Metals and Total Lead were reported in soil samples analyzed. The reported concentrations appear to represent background or trace elements that naturally occur in the subsurface; therefore, further environmental evaluation is not warranted at this time.

DISCUSSION OF FINDINGS

Based on geophysical data collected at the project site, a UST (located east of Al's Corner building) and septic tank (located west of Al's Corner building) are located beneath the subject property.

Soils encountered during this *Phase II Environmental Site Assessment* consisted of fine to medium grained sands. Physical evidence of contamination (i.e. petroleum hydrocarbon odor and/or staining) was observed at boring locations S2 through S4, and appeared to be from improper storage of used motor oil. Groundwater was not encountered at a depth of 50 feet below grade (the extent of our investigation); therefore, samples were not collected.

Based on laboratory analytical results from soil samples, petroleum hydrocarbon constituents and heavy metals were detected beneath the subject property. The maximum GRO concentration reported was 27 mg/kg (S7 at 0.5 feet bgs); the maximum DRO concentration reported was 2,200 mg/kg (S2 at 0.5 feet bgs), and the maximum MORO concentration reported was 20,000 mg/kg (S2 at 0.5 feet bgs). All other samples analyzed for GRO, DRO and MORO reported concentrations less than the laboratory reporting limit (0.10 mg/kg).

The reported heavy metals concentrations appear to represent trace or background levels inherent to local soils. Samples analyzed for CAM 17 Metals and/or Total Lead did not meet or exceed contaminant concentrations as outlined in the California Human Health Screening Levels (CHHSLs) for commercial use (Cal-EPA, 2005). The phrase "trace element" is rather loosely used in scientific literature to designate a number of elements that occur naturally in small concentrations. Their natural levels in soil vary widely, depending largely on the nature of parent materials from which soils form and also on soil-forming processes (Kearney, 1996).

CONCLUSIONS AND RECOMMENDATIONS

Based on information provided in this report, EEI has the following conclusions and recommendations:

- Based on geophysical data collected at the project site, a UST (located east of Al's Corner building) and septic tank (located west of Al's Corner building) are located beneath the subject property. Laboratory analytical results from soil samples collected adjacent to the UST and septic tank did not indicate a release of volatile fuel constituents. EEI recommends both the UST and septic tank be removed by a California-licensed tank removal contractor, in accordance to local and state regulations, and confirmation soil samples be collected to verify subsurface conditions prior to future site improvements.
- Based on laboratory analytical results, concentrations of volatile fuel hydrocarbons (i.e. gasoline, diesel and motor oil) have impacted near-surface soils in the area of boring locations S2 through S7. The vertical and lateral extent has not been sufficiently delineated; however, based on the nature of the release, appears to be limited to surficial soils (i.e., upper 18-inches). EEI recommends the impacted soils be excavated, properly characterized and disposed of, and verification samples be collected from the excavation bottom and sidewalls to confirm removals.
- Various 55-gallon capacity drums and plastic containers containing what appeared to be used
 motor oil and oily-water substances were noted throughout the project site. EEI recommends
 that the contents of these containers be properly characterized and disposed of prior to future site
 improvements.

- Various trash and debris, consisting of old and abandoned vehicles, scrap metal and construction debris was noted throughout the subject property. Although not considered an environmental concern, EEI recommends the trash/debris be removed from the site and disposed of prior to future site improvements. Further, the presence or likely presence of hazardous/waste material may be encountered during trash/debris removal and/or future site improvements; therefore, EEI recommends an experienced environmental consultant be onsite to observe removals and identify any suspect material requiring further testing, handling and/or disposal.
- A water well exists on the subject property. Although not considered an environmental concern, EEI recommends the well be properly abandoned according local and state guidelines prior to site improvement activities.

LIMITATIONS

This scope of work is based upon limited project site knowledge, information supplied by third parties, and project site access constraints. As always, this *Phase II Environmental Site Assessment Report* reflects EEI's best efforts to meet the expectations of County of Riverside's needs. Additionally, all invasive project site investigations are inherently based upon a small fraction of the actual subsurface data set, and conclusions are commonly based upon a variety of assumptions, which may or may not be accurate. No warranty; expressed or implied, is made upon our investigation, nor its results and conclusions, due to these inherent uncertainties and unknowns.

EEI appreciates the opportunity to provide services associated with this project site. If you have any questions or comments, please contact the undersigned at 619-668-9005.

Sincerely,

EEI

Prepared and Edited by:

Brand. Brennan

Brian R. Brennan, REA Project Manager

EEI

4730 Palm Avenue, Suite 213 La Mesa, California 91941-5264

619-668-9005

Reviewed by:

Bernard A. Sentianin, CPG, RG, REA

Principal Geologist

EEI

Attachments:

Figure 1 – Site Vicinity Map

Figure 2 -Boring Location Map

Table 1 - Laboratory Analytical Results for Soil Samples

Appendix A -Geophysical Investigation Report

Appendix B – Borehole Logs

Appendix C - Laboratory Analytical Results and Chain-of-Custody Documentation

Distribution:

(2) Addressee

REFERENCES

California Environmental Protection Agency (Cal-EPA), 2005, "Use of California Human Health Screening Levels (CHHSLs) in Evaluation of Contaminated Properties," dated January.

California Geological Survey (CGS), 2002, California Geomorphic Provinces Note 36, Electronic Copy, Revised December 2002.

California Regional Water Quality Control Board – Santa Ana Region 8 (CRWQCB), 1995, California State Water Resources Control Board Publication.


EEI, 2007, "Phase I Environmental Site Assessment, Riverside County Department of Facilities Management, 7010 Hamner Road, Corona, Riverside County, California," dated December 13, 2007.

Kearney Foundation Special Report, 1996, "Background Concentrations of Trace and Major Elements in California Soils," March.

Morton, D.M. and Gray Jr., C.H., 1995, Geologic Map of the Corona North 7.5' Quadrangle, Riverside and San Bernardino Counties, California, Version 1, Open-File Report 02-22, Electronic Database Website: http://wrgis.wr.usgs.gov/open-file/of02-022/crn_map.pdf.

United States Department of Agriculture (USDA) - Soil Conservation Service, 1974, Soil Survey of Riverside County, California, Corona Area.

FIGURES





Scale: 1'' = 1000'

0 FT 300 FT 1000 FT 2000 FT

Note: All locations are approximate

COUNTY OF RIVERSIDE - DEPARTMENT OF FACILITIES MANAGEMENT
Al's Corner
7010 Hamner Avenue
Corona, California


EEI Project No. COR-70413.2 Created on November 27, 2007



CREATED BY:	
SB	
REVISION DATE:	

REVISION NO.

FIGURE 1



TABLE


			•	TARLE 1	н -	SATORY ANALYTIC	LABORATORY ANALYTICAL RESULTS FOR SOIL SAMPLES	SAMPLES
			OLI	100 AUTOLI	7.4.7	LISEPA 8250B	TISEPA 8260B	USEPA 6010B
Comple ID	Date	Depth (feet	Crepo	USEFA eULJM (reported in mg/kg)	2/kg)	(reported in µg/kg)	(reported in µg/kg)	(reported in mg/kg)
Sampre II	Date	- (sgq	CRO) ARO	MORO	GRO/BTEX/MTBE	Other VOCs	Metals
			ONO		2000			Barium - 150; Chromium - 30; Cobalt - 12; Copper - 30; Lead
S1	11/19/2007	0.5	<0.10	<0.10	<0.10	<5.0-20	<5.0	48; Nickel - 19; Vanadium - 64; Zinc - 140; all other constituents less than laboratory reporting limit.
								Barium - 130; Chromium - 26; Cobalt - 12; Copper - 24; Lead
S2	11/19/2007	0.5	<0.10	2,200	20,000	<5.0-20	<5.0	12; Nickel - 15; Vanadium - 59; Zinc - 70; all other
							***************************************	CONSTITUENTS TESS THAI TAUDIATORY TOPOLITIES THANK
								Barium - 220; Cadmium - 3.6; Chromium - 360; Cobalt - 16;
ç	11/10/00/04	<i>y</i>	9	¥	410	<5.0-20	<5.0	Copper - 110; Lead - 93; Nickel - 50; Vanadium - 130; Zinc -
S	1007/61/11	7.0	?	f	2			320; all other constituents less than laboratory reporting limit.
							***************************************	Barrium - 150 Chromium - 28: Cobalt - 12: Copper - 25; Lead
						0	0 8/	68. Nickel 16. Vanadium - 60: Zinc - 180; all other
S	11/19/2007	0.5	0 9 9	28	011	00c-0.c>	0.57	constituents less than laboratory reporting limit.
								Barium - 110. Chromium - 21. Cohalt - 8.2. Copper - 22; Lead
				,	ć t	00000	~ ~	27. Nickel 15. Vanadium - 41; Zinc - 130; all other
SS	11/21/2007	0.5	7.3	<u> </u>	08c	000-0.0	?	constituents less than laboratory reporting limit.
								Barium - 140; Chromium - 41; Cobalt - 11; Copper - 22; Lead
Ì	20000	9 (0,00	3,6	246	<\$ 0-500	<5.0	21; Nickel - 18; Vanadium - 60; Zinc - 93; all other
9S	11/21/2007	C.O	0. 	3	2			constituents less than laboratory reporting limit.
							p-Isopropyltoluene - 14;	Barium - 140: Chromium - 40: Cobalt - 11; Copper - 25; Lead
		1	1	{	,	00000	all other constituents less	29. Nickel - 15: Vanadium - 54; Zinc - 150; all other
S7	11/21/2007	6.5	/7	76	907	0000	than laboratory reporting limit	constituents less than laboratory reporting limit.
		v	ΝΔ	NA	NA	<5.0-500	NA	Lead - 5.6; no other metals analyzed.
Ĺ	11/06/2007	10	VV	NA	NA	<5.0-500	NA	Lead - 6.2; no other metals analyzed.
ī	11/20/2001	2	VIV	NA	NA	<5.0-500	NA	Lead - 4.0; no other metals analyzed.
		CT	Y JAY	7. 7				Barium - 150; Chromium - 29; Cobalt - 13; Copper - 18; Lead
ç	7000/06/11	v	~0 10 ~0 10	010	\ \ \ \ \ \	<5.0-500	<5.0	3.2; Nickel - 15; Vanadium - 73; Zinc - 49; all other
7g	11/20/2007)	2	} 	;			constituents less than laboratory reporting limit.
Tohour	I aboutton, Deporting I imit	a I imit	0.10		0.10	5.0-500	5.0	1.0-5.0
Labour	atory terporati	5 mm	21.2			The state of the s		Barium - 63,000; Cadmium - 7.5; Chromium - 100,000;
	California	California Human Health Screening Levels (commercial)	alth Scree	ning Level	ls (comme	rcial)	NA	Cobalt - 3,200; Copper - 38,000; Lead - 3,500; Nickel -
)	·		· ·	16,000; Vanadium - 6,700; Zinc - 100,000
								ili: Motor Oil Range

bgs = below ground surface; BTEX = Benzene, Toluene, Ethylbenzene, Xylene; DRO = Diesel Range Organics; mg/kg = milligrams per kilogram; MORO = Motor Oil Range Organics; MTBE = Methyl Tert-Butyl Ether; NA = Not Analyzed/Applicable; µg/kg = micrograms per kilogram; USEPA = United States Environmental Protection Agency. It should be noted that the Chromium values reported in soil samples is Total Chromium, which is generally considered to be Chromium (III).

LTS (continued)		Jodan)		Lead - 6.4; no other metals analyzed.	Lead - 4.0; no other metals analyzed.	Lead - 5.0; no other metals analyzed.	Lead - 3.6; no other metals analyzed.	Lead - 4.8; no other metals analyzed.	Lead - 4.4; no other metals analyzed.	Barium - 93; Chromium - 64; Cobalt - 22; Copper - 40; Lead -	6.8; Nickel - 32; Vanadium - 95; Zinc - 62; all other	CONSTITUENTS TESS THAT TADOLARDLY TOPOLITIES THATE.	Lead - 4.0; no other metals analyzed.	Lead - 11; no other metals analyzed.	Lead - <3.0; no other metals analyzed.	Lead - <3.0; no other metals analyzed.	Lead - 8.4; no other metals analyzed.	Lead - 4.8; no other metals analyzed.	1.0-5.0	Barium - 63,000 Chromium - 100,000; Cobalt - 3,200;	Copper - 38,000; Lead - 3,500; Nickel - 16,000; Vanadium -	6,700; Zinc - 100,000
YTICAL RESU	USEPA 8260B	(reported in µg/kg)	Other VOCs	NA	NA	NA	NA	AN	NA		<5.0		NA	NA	NA	NA	NA	NA	0.5	V. C.	AA	
TABLE 1 - LABORATORY ANALYTICAL RESULTS (continued)	USEPA 8260B	(reported in µg/kg)	GRO/BTEX/MTBE	<5.0-500	<5.0-500	<5.0-500	<5.0-500	<5.0-500	<5.0-500		<5.0-500		<5.0-500	<5.0-500	<5.0-500	<\$ 0-500	<\$ 0-500	<5.0-500	005 005	0.0-0.0	rc(al)	
BLE 1-L	SM	g/kg)	MORO	NA	NA	NA	NA	NA	NA		<0.10		NA	NA	NA	NA	MA	NA	45.0	0.10	i Is fcomme	arrivan) et
TA	USEPA 8015M	(reported in m	DRO	NAN	NA	NA	NAN	NAN	NA		<0.10		N.	NA	NA	VIV	NA	VIV	INA	0.10	ning I eve	ming to re
A CONTRACTOR OF THE PROPERTY O			GRO	NA	NA	VN	NA	NA	VN	177	<0.10		AN	NAN AN	NA	VIV.	NA	NA VI	INA	0.10	olth Sore	satut Sere
		Depth (feet	(sāq	٠,	10	15	C. 4	10	15		ν,		3.5	10	15			01	<u> </u>	Limit	U.mon U.	nullali na
		Date	3		7.000/00/11	1007/07/11		70000011	7007/07/1		11/21/2007				11/21/2007		10000	/007/17/11		Laboratory Reporting Limit	Catternia Usuman Double Screening Levels (commercial)	Сашоппа
HIRITAGE TO THE PARTY OF THE PA		Cample ID	Sampre 11		D3	G		70	,		BS				B6		Î	B./		Labore		

logs = below ground surface; BTEX = Benzene, Toluene, Ethylbenzene, Xylene; DRO = Diesel Range Organics; mg/kg = milligrams per kilogram; MORO = Motor Oil Range Organics; MTBE = Methyl Tert-Butyl Ether; NA = Not Analyzed/Applicable; μg/kg = micrograms per kilogram; USEPA = United States Environmental Protection Agency. It should be noted that the Chromium values reported in soil samples is Total Chromium, which is generally considered to be Chromium (III).

APPENDIX A
GEOPHYSICAL INVESTIGATION REPORT



2075 Corte Del Nogal, Suite W Carlsbad, CA 92011

> Office: (760) 476-0492 Fax: (760) 476-0493

November 30, 2007

EEI 2195 Faraday Ave Suite K Carlsbad, CA 92008 Project / Invoice Number: 07-628

Attn: Mr. Tim Kelvas

Re: Geophysical Investigation at Subject Property Located at 7010 Hamner Ave., Corona, CA

This brief letter report is to present the findings of our geophysical surveys conducted over all accessible portions of a privately owned property located at 7010 Hamner Avenue within the City of Corona, California (Figure 1). The preparation for and the collection of geophysical data began at 0815 hours on November 19th, 2007 and was completed at 1400 hours on the same date. Unfortunately, due to circumstances beyond the control of all persons present on site (November 19) a small portion of the subject property could not be accessed until the following date of November 21st when an additional hour was spent in collecting EM-61 data without the use of a formal exploration grid being established. The purpose of the geophysical investigation(s) was to examine all accessible outdoor portions of the subject property to determine the presence, or absence of, any shallow subsurface objects (underground storage tanks (UST's)) and/or septic tanks that could possibly remain buried on the subject property.

At any given site the situation, geologic and cultural, may be such that one or more of the instruments may record excessive "noise", the ground may not provide sufficient contrasts, or there may be overlapping anomalies, for a given instrument to be effective. In this case the cultural (manmade) problems consisted of two (2) vehicles, several areas impacted by iron bollards and surface conductive debris. Summarily stated, there are generally instrumental limits and interpretational impediments.

<u>Survey Design</u> – Two (2) formal rectilinear grids were established on the subject property in order to guide the data acquisition of the electromagnetic (EM) data sets within two different portions of the property. The EM-61 MK2 data was collected in a south-north orientation throughout the former service station property and the mostly dirt and gravel areas found around the building structure.

Ground penetrating radar (GPR) traverses were conducted over portions of both grids in order to possibly identify the cause(s) of the EM anomalies observed in the data sets.

A Sensors & Software "Noggin" Ground Penetrating Radar unit produced the radar images; a Geonics model EM-61(advanced MK2 Model) instrument was used for EM sampling.

Partition CSP COR Cods

and entitle


Sth St Bus

24 A20


end natives

Bluff S

4th St







Brief Description of the Geophysical Methods Applied – The EM-61 MK2 instrument is a high resolution, time-domain device for detecting buried conductive objects. It consists of a powerful transmitter that generates a pulsed primary magnetic field when its coils are energized, which induces eddy currents in nearby conductive objects. The decay of the eddy currents, following the input pulse, is measured by the coils, which in turn serve as receiver coils. The decay rate is measured for two coils, mounted concentrically, one above the other. By making the measurements at a relatively long time interval (measured in milliseconds) after termination of the primary pulse, the response is nearly independent of the electrical conductivity of the ground. Thus, the instrument is a super-sensitive metal detector. Due to its unique coil arrangement (and a physical size of the antenna being 1 meter by a half meter) the response curve is a single well-defined positive peak directly over a buried conductive object. This facilitates quick and accurate location of targets. Conductive objects, to a depth of approximately 11 feet can be detected.

The magnetic gradiometer has two fluxgate magnetic fixed sensors that are passed closely to and over the ground. When not in close proximity to a magnetic object, that is, only in the earth's field, the instrument emits a sound signal at a low frequency. When the instrument passes over a buried iron or steel object, so that the field is significantly different at the two sensors, and locally magnetic gradient, the frequency of the emitted sound increases. Frequency is a function of the gradient between the two sensors.

The GPR instrument beams energy into the ground from its transducer/antenna, in the form of electromagnetic waves. A portion of this energy is reflected back to the antenna at any boundary in the subsurface across which there is an electrical contrast. The recorder continuously makes a record of the reflected energy as the antenna is traversed across the ground surface. The greater the electrical contrast, the higher the amplitude of the returned energy. The EM wave travels at a velocity unique to the material properties of the ground being investigated, and when these velocities are known, or closely estimated from ground conductivity values and other information, two-way travel times can be converted to depth.

Penetration into the ground and resolution of the GPR images produced are a function of ground electrical conductivity and dielectric constant. Images tend to be graphic, even at considerable depth, in sandy soils, but penetration and resolution may be limited in drastically more conductive clayey moist ground. At this particular investigation the ground conditions were somewhat favorable allowing for ground radar penetration down to a depth of 2.0 to 2.5 feet below the surface(s) scanned at 500 MHz.

<u>Interpretation</u> - Interpretation took place in real time as the survey progressed. Accordingly, the findings of our investigations were analyzed in the field and anomalies encountered within the search grid were investigated immediately. In addition, some digital photographs were taken during only a few operations at the site. The intent of this document is to demonstrate the procedure, and report the findings of the work.

Two different grids were utilized in this geophysical survey. Grid #1 will be discussed independently of Grid #2. Within each grid EM-61 data were collected at stations every 0.6 feet along south-north oriented survey lines spaced 5 feet apart.

The use of the EM-61 in a grid fashion allows for rapid examination of the subsurface in order to locate anomalously high zones of conductors beneath the dirt, asphalt and gravel surfaces of this site. Figure 2 is a view of Grid #1 looking north along Hamner Avenue, towards the intersection with Hamner and Schleisman Road.

Each EM anomaly was further investigated with the gradiometer and detailed with the EM antenna coil in an attempt to localize each of the anomalous areas found. There are a total of two (2) EM anomalies within Grid #1.

The EM "targets" location within the exploration grid will be discussed in X and Y coordinates. The grid coordinates in the X direction are the distances on the grid that correspond to movement along the west-to-east direction while the Y direction corresponds to distances along the south-to-north coordinates of the grid.

EM anomaly #1 is located at grid coordinate X = -15 - 0, Y = 120-132. During field investigation it became apparent that this anomaly was a septic tank located to the rear (west) of the main building structure (Figure 3). The septic tank had a large EM response due to the steel plates that cover the top of the tank(s). A PVC plastic pipeline was detected going from the building to the tank(s) by ground radar. Under the rock shown in Figure 3 is the sanitary sewer cleanout.

Figure 4 of this final report is a scaled map of the entire subject property investigated with the EM data from both grids #1 and #2 overlain on the map. After the EM data was downloaded in the field and fully processed, each location that indicated a strong subsurface conductor was investigated with the ground penetrating radar (GPR) in order to possibly identify the cause(s) of the subsurface "target", or EM anomaly.

EM anomaly #2 is located at grid coordinate X= 65', Y= 122'. The metallic (conductive) anomaly is not shallow enough to be imaged with the ground radar, indicating that the depth to the top of this anomaly is deeper than 2.5 feet. It should be noted that on two different ground radar passes a curved surface was imaged with the GPR system. This would be highly indicative of the round top surface of a possible underground storage tank (UST). GPR was able to define the lateral edges of the associated backfilled excavation in this area; this is marked in the field as shown in the upper left photo of Figure 5.

All other strong conductors found within Grid #1 were investigated and found to be associated with surface conductive vehicles (truck and bus) and cultural effect.


Grid #2 (please refer to Figure 4) did have some strong EM responses, but each response was found to be from surface debris and an abandoned school bus. No other EM "targets" are present within Grid #2 (Figure 6).


Because of conflicting intentions encountered on the original day of data gathering, the entire southwest quadrant of the subject property was investigated with the EM-61 MK2 antenna coil on Wednesday the 21st of November. This area of the property could easily be described as a small junk yard which is containing various vehicles (whole and in part) and surface conductive debris strewn almost everywhere. For this reason alone a formal exploration grid could not be established in this quadrant of the property. EM data was collected in a free-scan mode (EM coils energized in a constant "on" condition) walking through the area wherever access was feasible.


No detectable subsurface "targets" were found in the vicinity, but further investigation may be required for further assurances.

SHUBBLOROSKAPHS

Subject Property: 7010 Hammer Avenue Corona, California; Electromagnetic Grid #1








Ш






STATIONSTATIONSTA


Man Sat Contour Interval 180 Millsoft (NS)







SEF PHOTOGRAPHS 7010 Hamner Avenue


Corona, California















The same

STATE OF ORKAPES

Subject Property: 7010 Hamner Avenue Corona, California; Electromagnetic Grid #2





Subsurface Survey's professional personnel are trained and experienced and have completed thousands of projects since the company's inception in 1988. It is our policy to work diligently to bring this training and experience to bear to acquire quality data sets, which in turn, can provide clues useful in formulating our interpretations. Still, non-uniqueness of interpretations, methodological limitations, and non-target interferences are prevailing problems. Subsurface Surveys makes no guarantee either expressed or implied regarding the accuracy of the interpretations presented. And, in no event will Subsurface Surveys be liable for any direct, indirect, special, incidental, or consequential damages resulting from data sets, interpretations and opinions presented herewith.

All data generated on this project are in confidential file in this office, and are available for review by authorized persons at any time. The opportunity to participate in this investigation is very much appreciated. Please call, if there are questions.

Pol Mairesse

Gary W. Crosby, PhD, GP 960 Chief Geophysicist

Leopold "Pol" Mairesse Principal V.P., Sr. Geophysicist APPENDIX B BOREHOLE LOGS

, s	ا گ	EEI						BOREHOLI	E LOG		Number:	BI	
		xpertise	Service	Solutio	ns	Client:		County of River	side		Sheet:	l of	2
			10	Principal to a	۵.	Locatio	n:		Al's Comer	_			
Date	Started 11/20/		Date	Finishe				SWC Hamner Av	e & Schleisman	Rd, Corona, C	A		
EEI F		2007	EEI		Number:	Drill Rig	g/Sa	ampling Method:	Borehole Dia.:	Casing Dia.	: Cas	ing E	levation:
	Tim Ko	elvas		COR-70	0413.2	A PARTY NAMED IN COLUMN TWO IS NOT THE PARTY NAM		Direct Push	2"		(Alai	SL)	
	SAM	PLE LO	G	Start 7	ime			BOREHO	LE LOG			W	ELL LOG
Sam; Numt			VPID La	Depth In Feet	Symbol	Graphic Log		Geol (SoilType, Color, Grain, Minor So	ogic Description oil Component, Moista	rre, Density, Odor,	Etc.)	Wei	Il Description
2	0.5	915	0	1 2 3 4 5 6 7 8 9 10 11 12 12 13 14 15 16 17 18	SM			© 5' SAND, Reddish brow loose, no apparent odor or © 10' SAND, dark brown grained sand, dry, loose, r	rn, fine to medic staining greenish yellow so apparent odo	rm grained sa r, fine to medi r or staining	and, dry, um		
	4	0940	0	19 20 21 22				@ 20' SAND, red/yellow/ dry, loose, no apparent or	brown, fine to n dor or staining	nedium grain	sand,		
38.GPJ EELGDT 12/10/07	5	0950	0	23 24 25 26 27				@ 25' SAND, light brown dense, no apparent odor	n, fine to mediun or staining	n grain sand,	dry,		
BOREHOLE/WELL LOG BORING LOGS GPJ EELGDT	6	1005	0	28 29 30 31 32 33									
SOREHC	***************************************			34							. ,		

É EEI				BOREHOLI	E LOG	Nun	nber: B1	
Expertise S	ervice Se	olutions	Client:	County of Rive	rside	She	et: 2 of 2	
Date Started:	Date Fin		Location	SWC Hamner A	Al's Comer ve & Schleisman	Rd, Corona, CA		
11/20/2007 EEI Rep:	EEI Proj	1/20/2007 ject Number:	Drill Rig/	Sampling Method:	Borehole Dia.:	Casing Dia.:	Casing Elev	/ation:
Tim Kelvas SAMPLE LOG	1)R-70413.2 Start Time		Direct Push BOREHO	2" OLE LOG		WEI	L LOG
Sample Sample OVA/F Number Time (ppm	PID Lab	Depth USCS Symbol	Graphic Log	}	logic Description	are, Density, Odor, Etc.)	Well C	escription
ВОРЕНОLEMELL 1.0G. BORING I 0GS. GPJ. EEI.GDT 12/10/07	3 3 3 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	36		Total Boring Depth = 50' Ground water was not enwas backfilled with hydratasphalt patch.	countered. Upo	n completion, hol	e th	

ć		AEE	T						BOREHOLI	E LOG		Number:	В2		
				ervice	Solution	ns	Clien	t:	County of Rive	rside		Sheet:	l of	1	
Da	ite Stai	rted:		Date F	inishe	d:	Loca	tion:	: SWC Hamner Av	Al's Comer	Rd, Corona, C	Ά			
	11	/20/2007			11/20/2	2007								> F	-
E	El Rep:			1	-	lumber:	Drill		Sampling Method: Direct Push Geo Probe	Borehole Dia.:	Casing Dia. NA	: Cas (AM		evation:	-
		n Kelvas AMPLE	100		OR-70			D)	BOREHO		l BA		WE	ELL LOG	-
_	1		·····		Depth	T T				logic Description					4
	ample umber	Sample Time	OVA/F (ppm			USCS Symbol	Graph Log		(SoilType, Color, Grain, Minor S	oli Component, Moistu	re, Density, Odor,	Etc.)	Well	Description	
	1	1040	0		1 2 3 4 5 6 7 8 8				@ 5' SAND, light brown/ r-dry, slightly dense, no app	eddish, fine to m arent odor or sta	nedium graine iining	ed sand,		-	
	2	1050	0		9 10 11 12 13	SM			@ 10° SAND, light brown/ sand, minor silts, dry, sligh staining	reddish, fine to itly dense, no ap	medium grali oparent odor (ned or			
	3	1100	0		14 15 16 17				@ 15' SAND, light brown, sand, minor silts, dry, slight staining	/ reddish, fine to htly dense, no ap	medium grai oparent odor	ned or			-
0/07	4	1110			19 20 21 22 23 23				@ 20° SAND, light brown sand, dry, loose, no appa	/ reddish, fine to rent odor or stall	i medium grai ning	ined			
BOREHOLEWELL LOG BORING LOGS GPJ EELGDT 12/10/07			AND THE RESERVE THE PROPERTY OF THE PROPERTY O		24 25 26 27 28 29 30 31 32 33				Total Boring Depth = 24' Met refusal with Geo Prol Upon completion, hole with asi	as backfilled with	n hydrated be	ntonite			

	AEF	I		, , , , , , , , , , , , , , , , , , , 				esterorie	BOREHOLI	E LOG		Number	: B3	
36.5	971 		ervice	Soluti	ions	1	Client:		County of Rive	rside		Sheet:	l of	
							Locatio	n:		Al's Comer				
Date Sta	rted:		Date F						SWC Hamner Av	e & Schleisman	Rd, Corona,	CA		:
	/20/2007)/2007		n-## 01	~ (C	lampling Method:	Borehole Dia.:	Casing Dia	· Cas	ina El	evation:
EEI Rep:			1	•	: Number: 70413.2		`	•	rect Push Geo Probe	2"	NA		ISL)	
	m Kelvas			1				וע	BOREHO		1		WF	LLLOG
	SAMPLE	LOG			Time		<u> </u>							
Sample Number	Sample Time	OVA/P (ppm		Dept In Fee	Symbol		Graphic Log		Geo (SoilType, Color, Grain, Minor S	logic Description oil Component, Moisto	re, Density, Odor	Etc.)	Well	Description
2	1240	0		1 2 3 4 5 6 7 8 9 10 11					@ 5' SAND, dark brown/ r dry, slightly dense, no app @ 10' SAND, dark brown, sand, dry, slightly dense, t	arent odor or sta / reddish, fine to	medium gra	ined		
3	1250	0		12 13 14 15 16 17	SM				@ 15' SAND, dark brown sand, dry, slightly dense,	/ reddish, fine to no apparent odd	medium gra r or staining	ained		
4		C		20 21 22 23			- 0.00		@ 20' SAND, dark brown sand, minor silts, dry, slig staining	n/ reddish, fine to htly dense, no a	o medium gr pparent odo	ained r or		
ВОRЕНОСЕМЕЦ, LOG BORING LOGS GPJ EELGDT 12/10/07	1310		<u> </u>	24 25 26 27 28			-		@ 25' SAND, dark brown sand, minor silts, dry, slig staining	n/ reddish, fine to phtly dense, no a	o medium gr apparent odd	ained or or		
10G BORING 1C	1320		0	29 30 31			- (3) - (3)		@ 30° SAND, dark brow sand, minor silts, dry, slig staining	n/ reddish, fine t ghtly dense, no a	o medium gi apparent odd	rained or or		
SOREHOLEMELL 1				32 33 34	3				Total Boring Depth = 30' Met refusal with Geo Pro Upon completion, hole w chips and sealed with as	ibe. ras backfilled wit	h hydrated b	entonite		

		REE	I							BOREHOLI	ELOG		Number	: B4	
		7/1		ervice	Solutio	ns	Clie	ent:		County of River	rside		Sheet:	1 of	1
Ε	ate Sta			Date f	Inishe		Loc	cation	•	SWC Hamner Av	Al's Comer re & Schleisman	Rd, Corona, (CA		
E	II El Rep:	/20/2007 :		EEI P	11/20/2 roject h	2007 Number:	Dri	•		mpling Method:	Borehole Dia.:			ing E	levation:
lacksquare		m Kelvas SAMPLE	LOC		OR-70	······		D)ire	ect Push Geo Probe BOREHO	LE LOG	NA NA	<u> </u>	W	ELL LOG
	Sample	Sample	OVAP		Depth	USCS		phic			noic Description	- Density Odor	Ftc \	We	li Description
	Number	Time	(ppm) [20	Feet	Symbol	Li Est	>g -∏:∏	-	(SoilType, Color, Grain, Minor So	oil Component, Moistu	re, Density, Odor,	Etc. j	$\frac{1}{1}$	
		1345	0		1 2 3 4 5 6 7 8 8					@ 5' SAND, brown/ reddis slightly dense, no appareni	sh, fine to mediu t odor or stainìn	m grained sa	and, dry,		-
	2	1350	0		9 10 11 12 13					@ 10' SAND, brown/ redd minor silts, dry, slightly de	lish, fine to med nse, no apparen	ium grained : it odor or stai	sand, ining		
	3	1400	0		14 15 16 17	SM				@ 15' SAND, light brown, sand, minor silts, dry, slight staining	/ reddish, fine to htly dense, no a	medium gra pparent odor	ined or		
110/07	4	1405	C		19 20 21 22 23 23 23 24 25 25 25 25 25 25 25 25 25 25 25 25 25					@ 20' SAND, light brown sand, minor silts, dry, slig staining	/ reddish, fine to htly dense, no a	o medium gra pparent odor	nined or		
LOGS.GPJ EELGDT 12	5	1415)	24 25 26 27 27					@ 25' SAND, light brown sand, minor sills, dry, slig staining @ 30' SAND, light brown	thtly dense, no a	apparent odo	r or ained		
ADREHOLFAMELL LOG BORING LOGS GP.) EELGDT 12/10/07	6	1430		3	29 30 31 32 33 34					sand, minor silts, dry, slic staining Total Boring Depth = 30' Upon completion, hole w chips and sealed with as	antly dense, no a	apparent odo	f or		

EEI Expertise Serv		Client:		side Al's Comer	She	B5 eet: 1 of	
	Date Finished: 11/21/2007		SWC Hamner Ave	e & Schleisman l	Rd, Corona, CA		
11/21/2007 EEI Rep: E	EEI Project Number:	Drill Rig/S	Sampling Method:	Borehole Dia.:	Casing Dia.:	Casing E	levation:
Tim Kelvas	COR-70413.2	D	irect Push Geo Probe	2"	NA	<u> </u>	
SAMPLE LOG	Start Time		BOREHO	LE LOG		W	ELL LOG
Sample Sample OVA/PID Number Time (ppm)	Lab Depth USCS in Symbol	Graphic Log	Geok (SoilType, Color, Grain, Minor Sc	ogic Description ill Component, Moistu	re, Density, Odor, Etc.)) We	Il Description
1 0955 O O O O O O O O O O O O O O O O O O	1		@ 5' SAND, light brown/ reminor silts, dry, slightly der @ 10' SAND, light brown/ sand, minor silts, dry, slight staining @ 15' SAND, light brown, sand, minor silts, dry, slight staining Total Boring Depth = 18' Met refusal with Geo Profi Upon completion, hole was chips and sealed with aspending to the sand sealed with seal	reddish, fine to atly dense, no af reddish, fine to atly dense, no a set.	medium grained pparent odor or medium graine pparent odor or pparent odor or or pparent odor or o	d d	

25 S	A E E	T							-,	BOREHOLI	∃LOG		Nun	nber: Be	
			Service .	. Soluti	ions		С	lient:		County of River	rside		She	et: 1 of	1
Date S	tarted:	····	Date	Finish	ed:		L	ocatio	n:	SWC Hamner Av	Al's Comer re & Schleisman	Rd, Corona,	CA		
EEI Re	11/21/2007 p:		EELF	11/21 roject				rill Rig	g/S	ampling Method:	Borehole Dia.:	Casing Dia	a.:	Casing E	levation:
	Tim Kelvas		1	COR-					Di	rect Push Geo Probe	2"	NA_		(AMSL)	
	SAMPLE	LOG		Start	Time	2				BOREHO	LE LOG			W	ELL LOG
Sample Numbe		OVA/I (ppn	PID Lat	Dept in Fee	10	USCS Symbol		raphic Log		Geol (SoilType, Color, Grain, Minor Sc	ogic Description bil Component, Maistu	ire, Density, Odor	r, Etc.)	We	II Description
2	1030	0		1 2 3 4 5 5 6 7 7 8 8 9 10 11 11 12 13 14 15 16 17 18 19 20		SM				@ 5' SAND, brown/ reddis minor silts, dry, slightly den @ 10' SAND, brown/ redd minor silts, dry, dense, no @ 15' SAND, dark brown/ sand, minor silts, dry, dense @ 20' SAND, dark brown/ sand, minor silts, dry, dense with sand,	ish, fine to medi apparent odor of reddish, fine to se, no apparent	ium grained ium grained or staining o medium gra odor or stain	sand sained ning		
4	1045	()	21					-					-	
REHOLEMELL LOG BORING LOGS GP.1 EFI GDT 12/10/07		APARA ARANGAMAN MARINE MARINE MARINE MARINE MARINE ARANGAMAN ARANGAMAN ARANGAMAN MARINE MARINE MARINE MARINE M		22 23 24 25 26 27 28 30 31 32 33						Total Boring Depth = 20' Upon completion, hole wa chips and sealed with asp	is backfilled with halt patch.	h hydrated b	enton	ite -	

	AEE	T	Navarani I II				***************************************	BOREHOLI	E LOG	-	Number:	B7	
W. 5			ervice	Solutio	ns	Client:		County of River	rside		Sheet:	1 of 1	
Date Sta	arted:		Date F			Location	n:	SWC Hamner Av	Al's Comer e & Schleisman	Rd, Corona, C	:A		
EEI Rep	1/21/2007 ::		EEI Pi	11/21/ oject l	2007 Yumber:	Drill Rig/	/Sa	mpling Method:	Borehole Dia.:	Casing Dia.	: Casi		evation:
ļ	im Kelvas		(ı)413.2		Dire	ct Push Geo Probe BOREHO	Z"	NA NA			LL LOG
Samole	SAMPLE Sample	OVAP	ח	Start T Depth	T T	Graphic	T	Geol	ogic Description				Description
Number	Time	(ppm)	Lab	In Feet	Symbol	Log	-	(SoilType, Color, Grain, Minor So	ril Component, Moistu	re, Density, Odor, i	Etc.)	vves	Description
1	1055	0		1 2 3 4 5 6 7				夏 5' SAND, light brown/ re ninor silts, dry, dense, no i	eddish, fine to m apparent odor o	nedium graine r staining	ed sand,		
2	1100	0		9 10 11 12 13	SM			@ 10' SAND, dark brown/ sand, minor silts, dry, dens	reddish, fine to se, no apparent	medium graii odor or staini	ned ng		-
3	1105	0		14 15 16 17				@ 15' SAND, dark brown, sand, minor silts, dry, den	reddish, fine to se, no apparent	medium grai odor or staini	ned ing		
				19				@ 20' SAND, dark brown	/ reddish, fine to	medium grai	ined ina		
BOREHOLEWELL LOG BORING LOGS, GPJ ELI GDT 12/10/02/	1115			20 21 22 23 24 25 26 27 28 29 30 31 32 33				sand, minor silts, dry, den Total Boring Depth = 20' Upon completion, hole wa chips and sealed with asp	is backfilled with				

APPENDIX C
LABORATORY ANALYTICAL RESULTS
AND
CHAIN-OF-CUSTODY (COC) DOCUMENTATION

11 December 2007

Brian Brennan EEI - La Mesa 4730 Palm Avenue, Suite 213 La Mesa, CA 91941

allen Varyas

RE: Al's Corner

Enclosed are the results of analyses for samples received by the laboratory on 11/21/07 11:02. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Albert Vargas

Project Coordinator

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
S1-6"	T701526-01	Soil	11/19/07 11:30	11/21/07 11:02
S2-6"	T701526-03	Soil	11/19/07 11:47	11/21/07 11:02
\$3-6"	T701526-05	Soil	11/19/07 12:10	11/21/07 11:02
\$4-6"	T701526-07	Soil	11/19/07 12:22	11/21/07 11:02

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Wargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S1-6'' T701526-01 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Extractable Petroleum Hydrocarbons by	8015B								
C6-C12 (GRO)	ND	0.10	mg/kg	1	7112714	11/27/07	11/27/07	EPA 8015B	
C13-C28 (DRO)	ND	0.10	н	II	н	11	п	15	
C29-C40 (MORO)	ND	0.10	11	n	н	н	er	11	
Surrogate: p-Terphenyl		99.5 %	65-	135	"	•	"	"	
Metals by EPA 6010B									
Antimony	ND	3.0	mg/kg	1	7112808	11/28/07	12/05/07	EPA 6010B	
Silver	ND	2.0	н	49	11	*1	14	n	
Arsenic	ND	5.0	9	н	н	11	h	н	
Barium	150	1.0	н	q	11	0	Ħ	It	
Beryllium	ND	1.0	11	77	M	41	12/05/07	м	
Cadmium	ND	2.0)1	н	it	н	12/05/07	**	
Chromium	30	2.0	31	н	н	Ħ	15	н	
Cobalt	12	2.0	11	15	11	n	R	H	
Copper	30	1.0	11	n	n	н	ŭ	Ħ	
Lead	48	3.0	18	0	*1	v	II	If	
Molybdenum	ND	1.0	11	11	"	v .	, n	н	
Nickel	19	2.0	н	п	u	H	19	11	
Selenium	ND	5.0	89	41	11	th	В	н	
Thallium	ND	2.0	**	11	**	u	11	н	
Vanadium	64	5.0	11	н	н	tf	4	n	
Zine	140	1.0	13	п	11	15	te	IF	
Cold Vapor Extraction EPA 7470/7471									
Mercury	ND	0.10	mg/kg	1	7112809	11/28/07	11/30/07	EPA 7471A Soil	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

alleeTVargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S1-6" T701526-01 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Not
		SunStar La	aboratoi	ries, Inc.					
Volatile Organic Compounds by E									
Bromobenzene	ND	5.0	ug/kg	1	7112716	11/27/07	11/27/07	EPA 8260B	
Bromochloromethane	ND	5.0	,,	11	н	н	*1	ч	
Bromodichloromethane	ND	5.0	11	н	11	11	16	tf.	
Bromoform	ND	5.0	н	11	н	n	н	н	
Bromomethane	ND	5.0	11	н	11	41	tt	и	
n-Butylbenzene	ND	5.0	11	15	11	11	h	11	
sec-Butylbenzene	ND	5.0	11	н	Ð	11	†F	Ħ	
tert-Butylbenzene	ND	5.0	11	11	Ħ	М	н	n	
Carbon tetrachloride	ND ·	5.0	11	н	eı	ŧŧ	41	11	
Chlorobenzene	ND	5.0	11	17	ft	11	15	н	
Chloroethane	ND	5.0	"	†ŧ	н	н	Ħ	н	
Chloroform	ND	5.0	н	**	н	н	н	Ħ	
Chloromethane	ND	5.0	Ħ	м	tt.	ti ti	n	и	
2-Chlorotoluene	ND	5.0	n	tt	H	11	15	н	
4-Chlorotoluene	ND	5.0	u	n	н	н	н	н	
Dibromochloromethane	ND	5.0	13	н	11	tt	15	Ħ	
1,2-Dibromo-3-chloropropane	ND	5.0	**	**	**	и	H	H	
1,2-Dibromoethane (EDB)	ND	5.0	11	11	11	н	TJ	17	
Dibromomethane	ND	5.0	51	н	et	n	н	н	
1.2-Dichlorobenzene	ND	5.0	н	11	11	11	11	11	
1,3-Dichlorobenzene	ND	5.0	u	it	n	н	rs	Ħ	
1,4-Dichlorobenzene	ND	5.0	17	n	α	11	н	и	
Dichlorodifluoromethane	ND	5.0	11	н	#	**	n	13	
1.1-Dichloroethane	ND	5.0	н	17	n.	**	16	"	
1,2-Dichloroethane	ND	5.0	В	n	n	ij	н	ı)	
1,1-Dichloroethene	ND	5.0	11	u	0	11	11	н	
cis-1,2-Dichloroethene	ND	5.0	11	11	71	n	11	11	
trans-1,2-Dichloroethene	ND	5.0	н	11	11	Ħ	8	15	
1,2-Dichloropropane	ND	5.0	11	n	n	n	н	H	
* *	ND	5.0	TJ	n	*11	11	н	п	
1,3-Dichloropropane 2,2-Dichloropropane	ND	5.0	**	11	н	н	11	19	
	ND	5.0		н	Ħ	**	н	H	
1,1-Dichloropropene	ND	5.0		11	я	st	13	н	
cis-1,3-Dichloropropene	ND	5.0		n	11	11	п	n	
trans-1,3-Dichloropropene	ND ND	5.0 5.0		tr	11	н	11	0	
Hexachlorobutadiene	ND ND	5.0 5.0		H	н	ti	n	n	
Isopropylbenzene		5.0		el	11	11	ŧſ	н	
p-Isopropyltoluene	ND	5.0		5 E	13	н	11-	11	
Methylene chloride	ND			11	11	,	,,,	н	
Naphthalene	ND	5.0	ll .	11	n	н	11	19	
n-Propylbenzene	ND	5.0	11						

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Wargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S1-6'' T701526-01 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	borator	ies, Inc.					
Volatile Organic Compounds by E	PA Method 8260I	3							
Styrene	ND	5.0	ug/kg	1	7112716	11/27/07	11/27/07	EPA 8260B	
1,1,2,2-Tetrachloroethane	ND	5.0	11	11	11	М	n	н	
1,1,1,2-Tetrachloroethane	ND	5.0	n	11	н	24	n	11	
Tetrachloroethene	ND	5.0	19	8	11	н	Ħ	я	
1,2,3-Trichlorobenzene	ND	5.0	+1	n	н	ч	u	4	
1,2,4-Trichlorobenzene	ND	5.0	н	ĸ	#I	41	41	I)	
1,1,2-Trichloroethane	ND	5.0	19	н	tt.	18	10	D	
1,1,1-Trichloroethane	ND	5.0	11	ŧŧ	ø	Ħ	11	я	
Trichloroethene	ND	5.0	17	н	"	11	Th.	11	
Trichlorofluoromethane	ND	5.0	11	4	n	71	H	н	
1,2,3-Trichloropropane	ND	5.0	н	11	11	н	n	81	
1,3,5-Trimethylbenzene	ND	5.0	16	11	п	н	ţı	ff.	
1,2,4-Trimethylbenzene	ND	5.0	17	н	н	11	13	11	
Vinyl chloride	ND	5.0	15	0	н	ч	tr	17	
Benzene	ND	5.0	19	78	ŧŧ	45	41	16	
Toluene	ND	5.0	31	и	u	11	н	n	
Ethylbenzene	ND	5.0		#1	n	к	n	u	
m,p-Xylene	ND	5.0	19	**	11	н	11	41	
o-Xylene	ND	5.0	11	n	n	11	11	18	
Methyl tert-butyl ether	ND	20	19	11	11	31	ŧſ	H	
Surrogate: 4-Bromofluorobenzene		101 %	81-	118	n	ır	n	и	
Surrogate: Dibromofluoromethane		102 %	73-	127	n	"	"	"	
Surrogate: Toluene-d8		101 %		115	"	"	"	n	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tangos

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S2-6" T701526-03 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Note
Analyte	2000	SunStar La							
Extractable Petroleum Hydroc	carbons by 8015B								
C6-C12 (GRO)	ND	0.10	mg/kg	1	7112714	11/27/07	11/28/07	EPA 8015B	
C13-C28 (DRO)	2200	0.10	!!	11	NI .	11	Ħ	я	
C29-C40 (MORO)	20000	1.0_	17	10	11	м	17	lf	
Surrogate: p-Terphenyl		108 %	65-1	135	17	"	11	If	
Metals by EPA 6010B									
Antimony	ND	3.0	mg/kg	1	7112808	11/28/07	12/05/07	EPA 6010B	
Silver	ND	2.0	in	**	п	"	11	u	
Arsenic	ND	5.0	17	11	н	41	н	**	
Barium	130	1.0	11	и	11	н	11	if	
Beryllium	ND	1.0	11	at	м	н	12/05/07	п	
Cadmium	ND	2.0	59	π	tt	4	12/05/07	11	
Chromium	26	2.0	n	**	15	**	н	11	
Cobalt	12	2.0	Ħ	н	11	н	**	11	
Copper	24	1.0	11	п	н	11	п	и	
Lead	12	3.0	19	π	17	ĸ	tl	10	
Molybdenum	ND	1.0	н	н	п	п	ti	'n	
Nickel	15	2.0	15	0	11	19	н	n	
Selenium	ND	5.0	н	н	0	77	н	11	
Thallium	ND	2.0	11	11	11	n	4	11	
Vanadium	59	5.0	1#	0	н	n	π	н	
Zinc	70	1.0	11	TE	н	11	н	11	
Cold Vapor Extraction EPA 7	7470/7471								
Mercury	ND	0.10	mg/kg	1	7112809	11/28/07	11/30/07	EPA 7471A Soil	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tayas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S2-6'' T701526-03 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Note
: A Light y Do		SunStar La							
Volatile Organic Compounds by I	'			,					
Bromobenzene	ND	5.0	ug/kg	1	7112716	11/27/07	11/29/07	EPA 8260B	
Bromochloromethane	ND	5.0	H	rt	18	H	н	11	
Bromodichloromethane	ND	5.0	Ħ	0	41	Ht.	н	и	
Bromoform	ND	5.0	žī.	n	11	n	*1	11	
Bromomethane	ND	5.0	19	**	¥1	11	n	и	
n-Butylbenzene	ND	5.0	17	н	и	н		18	
sec-Butylbenzene	ND	5.0	#1	4	0	n	Ħ	н	
tert-Butylbenzene	ND	5.0	19	ч	n	н	11	и	
Carbon tetrachloride	· ND	5.0	11	n	u	U	н	н	
Chlorobenzene	ND	5.0	11	ti.	k)	ti	11	н	
Chloroethane	ND	5.0	11	tt.	tr	11	н	9	
Chloroform	ND	5.0	п	11	11	ય	11	II	
Chloromethane	ND	5.0	W.	n	11	n	**	0	
2-Chlorotoluene	ND	5.0	it	TI	n	11-	н	H	
4-Chlorotoluene	ND	5.0	##	н	н	FE	н	15	
Dibromochloromethane	ND	5.0	Ħ	15	Ħ	0	н	31	
1,2-Dibromo-3-chloropropane	ND	5.0	n	•	н	n	11	D	
1,2-Dibromoethane (EDB)	ND	5.0	37	н	74	11	н	t)	
Dibromomethane	ND	5.0	п	Ħ	U	ы	11	h	
1,2-Dichlorobenzene	ND	5.0	п	н	п	н	a	н	
1,3-Dichlorobenzene	ND	5.0	11	tf	41	*1	11		
1,4-Dichlorobenzene	ND	5.0	Ħ	11	н	11	н	11	
Dichlorodifluoromethane	ND	5.0	17	11	11	ęt	n	н	
1,1-Dichloroethane	ND	5.0	н	н	11	tt	М	¥f	
1,2-Dichloroethane	ND	5.0	18	11	τŧ	1)	М	81	
1,1-Dichloroethene	ND	5.0		н	н	n	н	19	
cis-1,2-Dichloroethene	ND	5.0	н	Ti-	Ħ	0	n	11	
trans-1,2-Dichloroethene	ND	5.0	v	н	u	п	е	re .	
1,2-Dichloropropane	ND	5.0	п	1)	н	16	м	16	
1,3-Dichloropropane	ND	5.0	11		11	h	t †	18	
2,2-Dichloropropane	ND	5.0	tt.	9	h	11	ħ	15	
1,1-Dichloropropene	ND	5.0		н	11	п	11	ıs	
	ND	5.0		11	Ħ	†t	ħ	8	
cis-1,3-Dichloropropene	ND ND	5.0		н	11	н	41	lı .	
trans-1,3-Dichloropropene	ND ND	5.0		n	н	**	Ŋ	11	
Hexachlorobutadiene	ND ND	5.0 5.0		н		н	v	16	
Isopropylbenzene		5.0 5.0		"	#	#I	*1	9	
p-Isopropyltoluene	ND	5.0 5.0		м	11,	н	15	n	
Methylene chloride	ND			.,	**	6	**	я	
Naphthalene	ND	5.0		,		,,	11	re	
n-Propylbenzene	ND	5.0	"	"	"				

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S2-6" T701526-03 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Volatile Organic Compounds by E	PA Method 8260I	3							
Styrene	ND	5.0	ug/kg	1	7112716	11/27/07	11/29/07	EPA 8260B	
1,1,2,2-Tetrachloroethane	ND	5.0	15	11	н	11	h	Ħ	
1,1,1,2-Tetrachloroethane	ND	5.0	n	TR	Ħ	п	н	n	
Tetrachloroethene	ND	5.0	11	ř†	n	n	11	н	
1,2,3-Trichlorobenzene	ND	5.0	"	11	11	11	11	41	
1,2,4-Trichlorobenzene	ND	5.0	۶I	19	и	tt	m	11-	
1,1,2-Trichloroethane	ND	5.0	11	н	n	н	11	н	
1,1,1-Trichloroethane	ND	5.0	19	H	15	и	**	54	
Trichloroethene	ND	5.0	1#	н	ii	н	fl	н	
Trichlorofluoromethane	ND	5.0	+1	u	ti	n	11	n	
1,2,3-Trichloropropane	ND	5.0	Ħ	11	н	- tt	н	15	
1,3,5-Trimethylbenzene	ND	5.0	11	н	п	н	я	н	
1,2,4-Trimethylbenzene	ND	5.0	11	u u	11	tl	11	я	
Vinyl chloride	ND	5.0)1	u	11	***	15	0	
Benzene	ND	5.0	19	44	n	15	н	n	
Toluene	ND	5.0	11	н	0	н	41	н	
Ethylbenzene	ND	5.0	ı)	47	11	ti	11	11	
m,p-Xylene	ND	5.0	11	11	n	0	п	**	
o-Xylene	ND	5.0	H	н	n	н	n	"	
Methyl tert-butyl ether	ND	20	11	Ħ	н	11	н	ji ji	
Surrogate: 4-Bromofluorobenzene		78.4 %	8.1	-118	"	н	н	5#	S-GC
Surrogate: Dibromofluoromethane		122 %	73	-127	"	rr r	"	"	
Surrogate: Toluene-d8		87.9 %	85	-115	н	11	tt	a	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tagas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S3-6'' T701526-05 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	borator	ies, Inc.					
Extractable Petroleum Hydrocarbons by	8015B								
C6-C12 (GRO)	ND	0.10	mg/kg	1	7112714	11/27/07	11/27/07	EPA 8015B	
C13-C28 (DRO)	45	0.10	17	н	11	*1	n	Ħ	
C29-C40 (MORO)	410	0.10_	п	ır	н	1r	н	19	
Surrogate: p-Terphenyl		86.0 %	65	135	rr	"	n	и	
Metals by EPA 6010B									
Antimony	ND	3.0	mg/kg	1	7112808	11/28/07	12/05/07	EPA 6010B	
Silver	ND	2.0	19	н	u	н	41	HF.	
Arsenic	ND	5.0	11	*1	и	N	17	Ħ	•
Barium	220	1.0	Ħ	н	н	n	н	11	
Beryllium	ND	1.0	13	it.	11	ft.	н	ti	
Cadmium	3.6	2.0	31	n	18	et	н	11	
Chromium	360	2.0	11	Ħ	н	11	н	н	
Cobalt	16	2.0	19	11	u	н	n	6	
Copper	110	1.0	н	h	15	ч	н	11	
Lead	93	3.0	**	10	н	11	ii.	в	
Molybdenum	3.0	1.0	н	н	11	н	15	11	
Nickel	50	2.0	н	н	н	45	н	Ħ	
Selenium	ND	5.0	11	0	n	и	п	н	
Thallium	ND	2.0	15	н	11	11	19	11	
Vanadium	130	5.0	17	15	11	н	ห	Ħ	
Zine	320	1.0	If	н	н	11	н	H	
Cold Vapor Extraction EPA 7470/7471									
Mercury	ND	0.10	mg/kg	1	7112809	11/28/07	11/30/07	EPA 7471A Soil	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

alle Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S3-6'' T701526-05 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Note
		SunStar La	aborato	ries, Inc.					
Volatile Organic Compounds by I	EPA Method 826						····		
Bromobenzene	ND	5.0	ug/kg	1	7112716	11/27/07	11/27/07	EPA 8260B	
Bromochloromethane	ND	5.0	19	11	tt	Ħ	н	tt	
Bromodichloromethane	ND	5.0	n	н	it	u	41	it.	
Bromoform	ND	5.0	н	11	н	н	н	н	
Bromomethane	ND	5.0	11	**	TP	#1	tt	н	
n-Butylbenzene	ND	5.0	11	U	11	n	14	ft	
sec-Butylbenzene	ND	5.0	f)	Ħ	†1	18	**	n	
tert-Butylbenzene	ND	5.0	11	TF.	: н	1t	н	н	
Carbon tetrachloride	ND	5.0	19 -	tt	t)	н	51	11	
Chlorobenzene	ND	5.0	"	H	11	Q.	11	n	
Chloroethane	ND	5.0	ŧŧ	i)	**	н	н	п	
Chloroform	ND	5.0	н .	74	11	H	5	19	
Chloromethane	ND	5.0	11	n	и	τř	11	н	
2-Chlorotoluene	ND	5.0	19	11	97	н	м	21	
4-Chlorotoluene	ND	5.0	11	n	**	н	11	ft	
Dibromochloromethane	ND	5.0	16	31	н	**	11	9	
1,2-Dibromo-3-chloropropane	ND	5.0	n	Ħ	0	н	Ħ	n	
1,2-Dibromoethane (EDB)	ND	5.0	11	31	**	11	16	н	
Dibromomethane	ND	5.0	11	*1	н	b	n	н	
1,2-Dichlorobenzene	ND	5.0	н	H	11	ri	*1	17	
1,3-Dichlorobenzene	ND	5.0	19	11	н	11	n	н	
1,4-Dichlorobenzene	ND	5.0	n	h	v	н	н	ч	
Dichlorodifluoromethane	ND	5.0	19	ti	11	ei .	11	15	
	ND	5.0	н	*16	н	n	и	н	
1,1-Dichloroethane	ND ND	5.0	11	н	11	н	n	11	
1,2-Dichloroethane	ND	5.0	19	11	*1	41	17	H	
1,1-Dichloroethene	ND ND	5.0	11	ft	11	и	n	я	
cis-1,2-Dichloroethene		5.0		1 1	11	и	ч	1f	
trans-1,2-Dichloroethene	ND	5.0 5.0		11	н	17	17	ĸ	
1,2-Dichloropropane	ND			н	**	п	n	21	
1,3-Dichloropropane	ND	5.0			11	II.	41	H	
2,2-Dichloropropane	ND	5.0		14		11	15	п	
1,1-Dichloropropene	ND	5.0		,,	"	ь.	n	н	
cis-1,3-Dichloropropene	ND	5.0			"		 n	 It	
trans-1,3-Dichloropropene	ND	5.0		11	n		11	,	
Hexachlorobutadiene	ND	5.0		16	•	10	,, n	"	
Isopropylbenzene	ND	5.0				11	n 11	r r	
p-Isopropyltoluene	ND	5.0		ध	11		11	ri If	
Methylene chloride	ND	5.0		it	Ħ	11		в.	
Naphthalene	ND	5.0		п	41	н	ĸ	Ħ	
n-Propylbenzene	ND	5.0	9	17	11	н	н	11	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S3-6" T701526-05 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Volatile Organic Compounds by E	PA Method 8260	В							
Styrene	ND	5.0	ug/kg	1	7112716	11/27/07	11/27/07	EPA 8260B	
1,1,2,2-Tetrachloroethane	ND	5.0	11	13	18	н	91	Ð	
1,1,1,2-Tetrachloroethane	ND	5.0	15	11	15	н	Ħ	н	
Tetrachloroethene	ND	5.0	11	и	tt	n	41	11	
1,2,3-Trichlorobenzene	ND	5.0	н	н	*	0	11	n	
1,2,4-Trichlorobenzene	ND	5.0	9	19	*1	n	М	iT .	
1,1,2-Trichloroethane	ND	5.0	H	11	11	н	q	11	
1,1,1-Trichloroethane	ND	5.0	11	n	н	11	11	п	
Trichloroethene	ND	5.0	11	u		11	н	н	
Trichlorofluoromethane	ND	5.0	п	**	16	н	n	11	
1,2,3-Trichloropropane	ND	5.0	11	н	н	11	**	it	
1,3,5-Trimethylbenzene	ND	5.0	11	0	4	Ħ	н	в	
1,2,4-Trimethylbenzene	ND	5.0	11	tt	łt	н	н	tf	
Vinyl chloride	ND	5.0	10	н	H	**	н	"	
Benzene	ND	5.0	11	tf	11	н	n	73	
Toluene	ND	5.0	51	n	Ħ	***	1t	N	
Ethylbenzene	ND	5.0	11	œ	11	11	n	11	
m,p-Xylene	ND	5.0	11	11	11	н	н	11	
o-Xylene	ND	5.0	11	n	н	ŧτ	11	N	
Methyl tert-butyl ether	ND	20	н	10	đ	n	н	"	
Surrogate: 4-Bromofluorobenzene		95.5 %	81	-118	11	н	"	"	
Surrogate: Dibromofluoromethane		101 %	73	-127	**	"	"	"	
Surrogate: Toluene-d8		101 %	85	-115	11	"	н	u	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S4-6'' T701526-07 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	borator	ies, Inc.					
Extractable Petroleum Hydrocarbons by	8015B								
C6-C12 (GRO)	ND	0.10	mg/kg	1	7112714	11/27/07	11/28/07	EPA 8015B	
C13-C28 (DRO)	28	0.10	19	a	ŧŧ	11	11	8	
C29-C40 (MORO)	110	0.10	19	н	н	Ħ	н	В	
Surrogate: p-Terphenyl		123 %	65-	135	tt .	n	Ħ	ø	
Metals by EPA 6010B									
Antimony	ND	3.0	mg/kg	1	7112808	11/28/07	12/05/07	EPA 6010B	
Silver	ND	2.0	11	**	н	#1	ft	15	
Arsenic	ND	5.0	11	. **	Ħ	н	н	и	
Barium	150	1.0	11	0	13	н	45	11	
Beryllium	ND	1.0	11	Ħ	11	н	Ħ	H	
Cadmium	ND	2.0	#	15	и	н	n	м	
Chromium	28	2.0	rı	11	0	11	45	1)	
Cobalt	12	2.0	7.6	N	†I	et	n	Ħ	
Copper	25	1.0	11	31	n	åt	,1	Ħ	
Lead	68	3.0	11	11	11	н	12	11	
Molybdenum	ND	1.0	11	н	Ħ	15	11	n	
Nickel	16	2.0	11	n	n	11	n	н	
Selenium	ND	5.0	11	47	41	•	н	n	
Thallium	ND	2.0	U	11	n	н	11	19	
Vanadium	60	5.0	71	н	п	11	4	н	
Zinc	180	1.0	t#	11	v	н	11	11	
Cold Vapor Extraction EPA 7470/7471									
Mercury	ND	0.10	mg/kg	1	7112809	11/28/07	11/30/07	EPA 7471A Soil	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tangos

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S4-6" T701526-07 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.			•		
Volatile Organic Compounds by E	EPA Method 826	0B							M-02
Bromobenzene	ND	5.0	ug/kg	1	7112716	11/27/07	11/27/07	EPA 8260B	
Bromochloromethane	ND	5.0		0	11	Ħ	n	19	
Bromodichloromethane	ND	5.0	11	я	Ħ	4	łŧ	н	
Bromoform	ND	5.0	H	н	n	н	н	Ħ	
Bromomethane	ND	5.0	19	11	11	n	u u	11	
n-Butylbenzene	ND	5.0	**	11	n	tt.	n	и	
sec-Butylbenzene	ND	5.0	15	19	19	н	н	łt	
tert-Butylbenzene	ND	5.0	1\$	4	!1	ţţ	н	31	
Carbon tetrachloride	ND	5.0	Ħ	11	11	н	н	11	
Chlorobenzene	ND	5.0	н	н	11	ti-	11	"	
Chloroethane	ND	5.0	11	tt	n	R	м	41	
Chloroform	ND	5.0	Ħ	13	#1	и	4	н	
Chloromethane	ND	5.0	15	н	н	44	11	н	
2-Chlorotoluene	ND	5.0	11	10	11	н	n		
4-Chlorotoluene	ND	5.0	и	0	74	U	•	H	
Dibromochloromethane	ND	5.0	11	н	И	#1	h	и	
1.2-Dibromo-3-chloropropane	ND	5.0	п	11	11	n	n	11	
1,2-Dibromoethane (EDB)	ND	5.0	19	Ħ	n	10	0	'n	
Dibromomethane	ND	5.0)1	н	U	**	н	11	
1,2-Dichlorobenzene	ND	5.0	19	11	11	n	11	11	
1,3-Dichlorobenzene	ND	5.0	**	н	н	11	**	rt	
1,4-Dichlorobenzene	ND	5.0	11	0	10	н	n	11	
Dichlorodifluoromethane	ND	5.0	**	π	**	q	*1	"	
1,1-Dichloroethane	ND	5.0		H	н	0	11	н	
1.2-Dichloroethane	ND	5.0	19	e	n	м	n	11	
1,1-Dichloroethene	ND	5.0	и, ,	Ħ	n	ŧı	11	н	
cis-1,2-Dichloroethene	ND	5.0	13	11	n	11	H	51	
trans-1,2-Dichloroethene	ND	5.0		n	11	н	и	11	
1,2-Dichloropropane	ND	5.0		h	н	er	11	п	
1,3-Dichloropropane	ND	5.0	19	u	•	1t	n	n	
2,2-Dichloropropane	ND	5.0		11	tt	n	н	Э	
1,1-Dichloropropene	ND	5.0		н	н.	17	17	le .	
cis-1,3-Dichloropropene	ND	5.0	1\$	n	ti	rŧ	IX	H	
trans-1,3-Dichloropropene	ND	5.0		11	16	н	н	H*	
Hexachlorobutadiene	ND	5.0		н	n	et.	11	Ħ	
Isopropylbenzene	ND	5.0		a	tr	11	н	н	
p-Isopropyltoluene	ND	5.0		Ħ	13	н	n	et	
Methylene chloride	ND	5.0		н	п	ŧŧ	u	FE	
Naphthalene	ND	5.0		н	ŧγ	11	πŧ	H	
n-Propylbenzene	ND	5.0		11	11	n	н	н	
n-r ropyroenzene	ND	5.0	•						

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Comer

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

S4-6'' T701526-07 (Soil)

Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Note
	SunStar La	borator	ies, Inc.					
								M-02
ND	5.0	ug/kg	1	7112716	11/27/07	11/27/07	EPA 8260B	
ND	5.0	н	ŧı	н	н	#	н	
ND	5.0	13	8	et	11	Ħ	श	
ND	5.0	11	11	i.	p	41	11	
ND	5.0	19	n	н	н	n	**	
ND	5.0	†1	15	(t	ıı	£ tt	11	
ND	5.0	‡1	n	11	0	*1	11	
ND	5.0	11	н	Ħ	Ħ	Ħ	Ħ	
ND	5.0	11	0	rt	н	н :	Ħ	
ND	5.0	11	75	**	11	41	0	
ND	5.0	19	н	н	н	н	н	
ND	5.0	11	41	NF.	1t	fr .	tî .	
ND	5.0	19	Ħ	11	н	я	н	
ND	5.0	*1	n	**	n	8	**	
ND	5.0	19	п	44	0	11	H	
ND	5.0	11	Ħ	н	n	n	n	
ND	5.0	11	•	u	0	ø .	11	
ND	5.0	17	п	н	11	71	п	
ND	5.0	и	*1	31	11	н	n	
ND	20	o	11	71	U	11	11	
	96.4 %	81	-118	11	"	11	**	
				"	"	"	"	
				п	"	11	**	
	PA Method 82601 ND ND ND ND ND ND ND ND ND N	Result Limit SunStar La PA Method 8260B ND 5.0 ND 5.0 <	ND SunStar Laborator	Result Limit Units Dilution	ND Substant Subs	SunStar Laboratories, Inc. Prepared	ND 5.0 " " " " " " " " " " " " "	ND S.0 ND S.0 ND S.0 ND S.0 ND S.0 ND ND S.0 ND S.0 ND ND ND S.0 ND ND S.0 ND ND S.0 ND ND S.0 ND ND ND S.0 ND ND ND S.0 ND ND ND S.0 ND ND ND ND ND ND ND N

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

alber Wargas

4730 Palm Avenue, Suite 213 La Mesa CA, 91941 Project: Al's Corner

Project Number: [none]
Project Manager: Brian Brennan

Reported: 12/11/07 09:52

RPD

%REC

Extractable Petroleum Hydrocarbons by 8015B - Quality Control SunStar Laboratories, Inc.

Reporting

Spike

Source

Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
			Prepared	& Analyz	ed: 11/27/	07			
92.4		mg/kg	100		92.4	65-135			
ND	0.10	Н							
ND	0.10	11							
ND	0.10	в							
			Prepared	& Analyz	ed: 11/27/	07			
94.7		mg/kg	100		94.7	65-135		-	
470	0.10	н	500		93.7	75-125			
Sc	ource: T70152	21-01	Prepared	: 11/27/07	Analyzed	i: 11/28/07			
106	A./	mg/kg	100		106	65-135			
490	0.10	1	500	ND	97.5	75-125			
Se	ource: T7015	21-01	Prepared	: 11/27/07	Analyze	d: 11/28/07			
108		mg/kg	100		108	65-135			
580	0.10	Н	500	ND	116	75-125	16.9	20	
	92.4 ND ND ND 94.7 470 So 106 490 Sc	92.4 ND 0.10 ND 0.10 ND 0.10 ND 0.10 94.7 470 0.10 Source: T70152 106 490 0.10 Source: T70152	Result Limit Units 92.4 mg/kg ND 0.10 " ND 0.10 " ND 0.10 " Source: T701521-01 106 mg/kg 490 0.10 " Source: T701521-01 108 mg/kg	Result Limit Units Level Prepared 92.4 mg/kg 100 ND 0.10 " ND 0.10 " ND 0.10 " Prepared 94.7 mg/kg 100 470 0.10 " 500 Source: T701521-01 Prepared 106 mg/kg 100 490 0.10 " 500 Source: T701521-01 Prepared 108 mg/kg 100	Result Limit Units Level Result	Result Limit Units Level Result %REC Prepared & Analyzed: 11/27// 92.4 mg/kg 100 92.4 ND 0.10 " ND 0.10 " Prepared & Analyzed: 11/27// 94.7 mg/kg 100 94.7 470 0.10 " 500 93.7 Source: T701521-01 Prepared: 11/27/07 Analyzed: 106 490 0.10 " 500 ND 97.5 Source: T701521-01 Prepared: 11/27/07 Analyzed: 108 108 108 108	Prepared & Analyzed: 11/27/07	Result Limit Units Level Result %REC Limits RPD Prepared & Analyzed: 11/27/07 92.4 mg/kg 100 92.4 65-135 ND 0.10 " ND 0.10 " ND 0.10 " Prepared & Analyzed: 11/27/07 Prepared: 11/27/07 94.7 mg/kg 100 94.7 65-135 470 0.10 " 500 93.7 75-125 Source: T701521-01 Prepared: 11/27/07 Analyzed: 11/28/07 106 mg/kg 100 106 65-135 490 0.10 " 500 ND 97.5 75-125 Source: T701521-01 Prepared: 11/27/07 Analyzed: 11/28/07 108 mg/kg 100 108 65-135	Prepared & Analyzed: 11/27/07

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Vargas

4730 Palm Avenue, Suite 213

Project: Al's Corner

Project Number: [none] Project Manager: Brian Brennan

Reported: 12/11/07 09:52

La Mesa CA, 91941

Metals by EPA 6010B - Quality Control

SunStar Laboratories, Inc.

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 7112808 - EPA 3051										
Blank (7112808-BLK1)				Prepared:	11/28/07	Analyzed	: 12/03/07			
Antimony	ND	3.0	mg/kg							
Silver	NĐ	2.0	р							
Arsenic	ND	5.0	41							
Barium	ND	1.0	u							
Beryllium	ND	1.0	IF							
Cadmium	ND	2.0	ti							
Chromium	ND	2.0	H							
Cobalt	ND	2.0	н							
Copper	ND	1.0	n							
Lead	ND	3.0	म							
Molybdenum	ND	1.0	TI .							
Nickel	ND	2.0	14							
Selenium	ND	5.0	п							
Thallium	ND	2.0	н							
Vanadium	ND	5.0	n							
Zinc	ND	1.0	n							
LCS (7112808-BS1)				Prepared	: 11/28/07	Analyze	d: 12/03/07	7		
Arsenic	118	5.0	mg/kg	100		118	75-125			
Barium	113	1.0	и	100		113	75-125			
Cadmium	112	2.0	11	100		112	75-125			
Chromium	112	2.0	Ħ	100		112	75-125			
Lead	111	3.0	II	100		111	75-125			
Matrix Spike (7112808-MS1)	Se	ource: T7015	20-01	Prepared	: 11/28/07	Analyze	d: 12/03/0	7		QM-07
Arsenic	90.4	5.0	mg/kg	100	ND	90.4	75-125			
Barium	278	1.0	н	100	233	45.6	75-125			QM-0
Cadmium	86.3	2.0	n	100	4.80	81.5	75-125			
Chromium	185	2.0	p	100	282	NR	75-125			QM-0*
Lead	775	3.0	tì	100	954	NR	75-125			QM-0'

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

Metals by EPA 6010B - Quality Control SunStar Laboratories, Inc.

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes

Batch 7112808 - EPA 3051

Matrix Spike Dup (7112808-MSD1)	Sourc	e: T70152	0-01	Prepared:	Analyze	d: 12/03/07			QM-07	
Arsenic	105	5.0	mg/kg	100	ND	105	75-125	15.1	20	
Barium	354	1.0	ŧı	100	233	121	75-125	23.9	20	QM-07
Cadmium	97.3	2.0	и	100	4.80	92.5	75-125	12.0	20	
Chromium	179	2.0	B	100	282	NR	75-125	3.32	20	QM-07
Lead	1020	3.0	н	100	954	60.8	75-125	26.8	20	QM-07

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Albert Vargas, Project Coordinator

allen Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

Cold Vapor Extraction EPA 7470/7471 - Quality Control SunStar Laboratories, Inc.

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Part - 7112000 EDA 7471A Soil										

Blank (7112809-BLK1)				Prepared:	11/28/07	Analyzed:	11/30/07			
Mercury	ND	0.10	mg/kg							
LCS (7112809-BS1)				Prepared:	11/28/07	Analyzed:	11/30/07			
Mercury	0.446	0.10	mg/kg	0.417		107	80-120			
Matrix Spike (7112809-MS1)	Sour	ce: T70153	2-16	Prepared:	11/28/07	Analyzed:	11/30/07	····-		****
Mercury	0.392	0.10	mg/kg	0.417	ND	94.1	75-125			
Matrix Spike Dup (7112809-MSD1)	Sour	ce: T70153	32-16	Prepared:	11/28/07	Analyzed:	11/30/07			
Mercury	0.448	0.10	mg/kg	0.417	ND	108	75-125	13.3	20	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

alle Tayas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

Volatile Organic Compounds by EPA Method 8260B - Quality Control SunStar Laboratories, Inc.

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes

Batch 7112716 - EPA 5030 GCMS

Blank (7112716-BLK1)	1000	Prepared & Analyzed: 11/27/07									
Surrogate: 4-Bromofluorobenzene	7.96		ug/kg	8.00	99.5	73.5-115					
Surrogate: Dibromofluoromethane	7.81		11	8.00	97.6	79-126					
Surrogate: Toluene-d8	7.97		11	8.00	99.6	85.8-113					
Bromobenzene	ND	2.0	. #								
Bromochloromethane	ND	2.0	н								
Bromodichloromethane	ND	2.0	н								
Bromoform	ND	2.0	Ħ								
Bromomethane	ND	2.0	II								
n-Butylbenzene	ND	2.0	40								
sec-Butylbenzene	ND	2.0	и								
tert-Butylbenzene	ND	2.0	IF								
Carbon tetrachloride	ND	2.0	II								
Chlorobenzene	ND	2.0	Ħ								
Chloroethane	ND	2.0	E4								
Chloroform	ND	2.0	ti								
Chloromethane	ND	2.0	11								
2-Chlorotoluene	ND	2.0	tt								
4-Chlorotoluene	ND	2.0	rt .								
Dibromochloromethane	ND	2.0	B								
1,2-Dibromo-3-chloropropane	ND	2.0	H								
1,2-Dibromoethane (EDB)	ND	2.0	Ħ								
Dibromomethane	ND	2.0	B								
1,2-Dichlorobenzene	ND	2.0	11								
1,3-Dichlorobenzene	ND	2.0	23								
1,4-Dichlorobenzene	ND	2,0	Н								
Dichlorodifluoromethane	ND	2.0	tt								
1,1-Dichloroethane	ND	2.0	It								
1,2-Dichloroethane	ND	2.0	n								
1,1-Dichloroethene	ND	2.0	ır								
cis-1,2-Dichloroethene	ND	2.0	n								
trans-1,2-Dichloroethene	ND	2.0	Ħ								
1,2-Dichloropropane	ND	2.0	Ħ								
1,3-Dichloropropane	ND	2.0	я								
2,2-Dichloropropane	ND	2.0	н								
1,1-Dichloropropene	ND	2.0	rt								
cis-1,3-Dichloropropene	ND	2.0	П								
trans-1,3-Dichloropropene	ND	2.0	li .								
Hexachlorobutadiene	ND	2.0	II								
Isopropylbenzene	ND	2.0	H	•							
p-Isopropyltoluene	ND	2.0	H								
Methylene chloride	ND	2.0	11								

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Wargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Reporting

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

RPD

%REC

Volatile Organic Compounds by EPA Method 8260B - Quality Control SunStar Laboratories, Inc.

Spike

Source

Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch 7112716 - EPA 5030 GCMS										
Blank (7112716-BLK1)				Prepared	& Analyz	ed: 11/27/0)7			
Naphthalene	ND	2.0	ug/kg							
n-Propylbenzene	ND	2.0	23							
tyrene	ND	2.0	H							
,1,2,2-Tetrachloroethane	ND	2.0	ıt							
,1,1,2-Tetrachloroethane	ND	2.0	si							
etrachloroethene	ND	2.0	П							
,2,3-Trichlorobenzene	ND	2.0	п							
,2,4-Trichlorobenzene	ND	2.0	Ħ							
,1,2-Trichloroethane	ND	2.0	11							
,1,1-Trichloroethane	ND	2.0	n							
richloroethene	ND	2.0	#							
richlorofluoromethane	ND	2.0	IF.							
,2,3-Trichloropropane	ND	2.0	u							
,3,5-Trimethylbenzene	ND	2.0	0							
,2,4-Trimethylbenzene	ND	2.0	H							
inyl chloride	ND	2.0	Ħ							
Benzene	ND	2.0	18							
oluene	ND	2.0	tt							
Ethylbenzene	ND	2.0	#							
n,p-Xylene	ND	4.0	11							
-Xylene	ND	2.0	н							
Methyl tert-butyl ether	ND	5.0	11							
LCS (7112716-BS1)				Prepared	l & Analyz	zed: 11/27/	07			
Surrogate: 4-Bromofluorobenzene	7.63		ug/kg	8.00		95.4	73.5-115	•		
Surrogate: Dibromofluoromethane	7.99		- "	8.00		99.9	79-126			
Surrogate: Toluene-d8	8.06		"	8.00		101	85.8-113			
Chlorobenzene	96.8	2.0	it	100		96.8	75-125			
1,1-Dichloroethene	98.2	2.0	41	100		98.2	75-125			
Prichloroethene	91.6	2.0	n	100		91.6	75-125			
Benzene	98.8	2.0	Ħ	100		98.8	75-125			
Toluene	98.6	2.0	11	100		98.6	75-125			

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

alleer Vargas

4730 Palm Avenue, Suite 213 La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/11/07 09:52

Volatile Organic Compounds by EPA Method 8260B - Quality Control SunStar Laboratories, Inc.

		Reporting	W.W. 14.	Spike	Source	e/DCC	%REC	RPD	RPD Limit	Notes
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	NIJ)	LHIIN	140102
Batch 7112716 - EPA 5030 GCMS										
Matrix Spike (7112716-MS1)	Sou	ırce: T70152	1-01	Prepared	& Analyze	ed: 11/27/	07			
Surrogate: 4-Bromofluorobenzene	7.97		ug/kg	8.00		99.6	73.5-115			
Surrogate: Dibromofluoromethane	7.86);	8.00		98.2	79-126			
Surrogate: Toluene-d8	8.00		"	8.00		100	85.8-113			
Chlorobenzene	96.4	2.0	zi	100	ND	96.4	75-125			
1,1-Dichloroethene	96.2	2.0	и	100	ND	96.2	75-125			
Trichloroethene	86.8	2.0	y	100	ND	86.8	75-125			
Benzene	94.4	2.0	Ħ	100	ND	94.4	75-125			
Toluene	94.1	2.0	11	100	ND	94.1	75-125			
Matrix Spike Dup (7112716-MSD1)	So	urce: T70152	1-01	Prepared	& Analyz	ed: 11/27/	′07	107		
Surrogate: 4-Bromofluorobenzene	7.87		ug/kg	8.00		98.4	73.5-115	.,		
Surrogate: Dibromofluoromethane	7.81		"	8.00		97.6	79-126			
Surrogate: Toluene-d8	8.14		11	8.00		102	85.8-113			
Chlorobenzene	98.4	2.0	If	100	ND	98.4	75-125	2.11	20	
1,1-Dichloroethene	99.8	2.0	н	100	ND	99.8	75-125	3.73	20	
Trichloroethene	89.6	2.0	R	100	ND	89.6	75-125	3.06	20	
Benzene	98.8	2.0	51	100	ND	98.8	75-125	4.56	20	
Toluene	97.8	2.0	H	100	ND	97.8	75-125	3.81	20	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tagas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported:

12/11/07 09:52

Notes and Definitions

S-GC Surrogate recovery outside of established control limits. The data was accepted based on valid recovery of the remaining

surrogate(s).

QM-07 The spike recovery and or RPD was outside acceptance limits for the MS and/or MSD. The batch was accepted based on

acceptable LCS recovery.

M-02 Multiple analysis yielded poor internal standard and/or surrogate recoveries due to matrix effect. Results reported are from the

most complete recovery of internal standards, however, recoveries were not within the acceptable limits of the method.

DET Analyte DETECTED

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis

RPD Relative Percent Difference

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Albert Vargas, Project Coordinator

allee Targas

Page 21 of 21

591:01 TO 12 va Brian R. Brennan

SunStar Laboratories, Inc. 3002 Dow Ave., Sie. 212 Tustin, CA 92780 714-505-4010

Project Manager. Address Phone: Client:

Client Project #: Collect #: 2 coc 71369 Page:_ Project Name Collector: Batch #:__ Date:

Total # of containers	y com
Comments/Preservative	email reals to
8015M (diesel)	Total # of containers Total # of containers Seals intact? Y/N/NA Received good condition/cold Turn around time
8260 + OXY only 8250 BTEX, OXY only 8270 8270 8021 BTEX	Date / Time //21/07 /1. Date / Time Pickup
Container S260	ived by: (signature) ived by: (signature) ived by: (signature) Return to client
Sample Type	Rece Rece
Date & Sampled Time 1177/07 1/35 1/35 1/35	Date Time
Sample 1D 57 - 6 72 - 78 52 - 6 53 - 6 53 - 6 53 - 78 53 - 78 53 - 78 53 - 78 54 - 18 54 - 18	Refinquished by: (signature) Befinquished by: (signature) Refinquished by: (signature) Sample disposal instructions:

10 December 2007

Brian Brennan

EEI - La Mesa

4730 Palm Avenue, Suite 213

aller Vargas

La Mesa, CA 91941

RE: Al's Corner

Enclosed are the results of analyses for samples received by the laboratory on 11/21/07 12:00. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Albert Vargas

Project Coordinator

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]
Project Manager: Brian Brennan

Reported: 12/10/07 16:42

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
S5-6"	T701524-01	Soil	11/21/07 10:20	11/21/07 12:00
S6-6"	T701524-03	Soil	11/21/07 10:25	11/21/07 12:00
S7-6"	T701524-05	Soil	11/21/07 10:48	11/21/07 12:00

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Albert Vargas, Project Coordinator

aller Tangas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 16:42

S5-6" T701524-01 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	borator	ies, Inc.					
Extractable Petroleum Hydrocarbons by	8015B								
C6-C12 (GRO)	7.3	0.10	mg/kg	1	7112714	11/27/07	11/27/07	EPA 8015B	
C13-C28 (DRO)	71	0.10	12	Ħ	n	11	#1	н	
C29-C40 (MORO)	580	0.10	15	11	111	17	11	11	
Surrogate: p-Terphenyl		112 %	65-1	135	"	"	"	"	
Metals by EPA 6010B									
Antimony	ND	3.0	mg/kg	1	7112808	11/28/07	12/05/07	EPA 6010B	
Silver	ND	2.0	19	n	11	и	tl	н	
Arsenic	ND	5.0	Ŧ1	n	М	tr.	41	и	
Barium	110	1.0	19	н	Ħ	**	11	Ħ	
Beryllium	ND	1.0	n	н	н	11	12/05/07	31	
Cadmium	ND	2.0	10	•	41	M	12/05/07	π	
Chromium	21	2.0	19	31	**	н	1)	et	
Cobalt	8.2	2.0	Ħ	n	п	n	16	TF.	
Copper	22	1.0	н	n	В	H	n	н	
Lead	27	3.0	39	**	15	н	15	tt	
Molybdenum	ND	1.0	**	**	H	11	h	н	
Nickel	15	2.0	ti.	10	11	11	11	n	
Selenium	ND	5.0	II	Ħ	†I	0	19	н	
Thallium	ND	2.0	U	n	Ħ	n	ıı	в	
Vanadium	41	5.0	11	n	н	н	ŧı	u	
Zinc	130	1.0	11	ŧr	r1	n	11	11	
Cold Vapor Extraction EPA 7470/7471									
Mercury	ND	0.10	mg/kg	1	7112809	11/28/07	11/30/07	EPA 7471A Soil	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tangas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 16:42

S5-6'' T701524-01 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Note
		SunStar L	aborator	ies, Inc.					
Volatile Organic Compounds by I	EPA Method 826	0B							
Bromobenzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/30/07	EPA 8260B	
Bromochloromethane	ND	5.0	79	.01	n	н	स	н .	
Bromodichloromethane	ND	5.0	H	Ħ	ei	n	ti .	l7	
Bromoform	ND	5.0	18	н	tt	n	н	н	
Bromomethane	ND	5.0		*1	11	H	11	19	
n-Butylbenzene	ND	5.0	19	ŧţ	*1	19	n	н	
sec-Butylbenzene	ND	5.0	н	17	н	т	ti	11	
tert-Butylbenzene	ND	5.0	19	Ħ	u	n	11	#t	
Carbon tetrachloride	ND	5.0	11	16	и	н	n	a	
Chlorobenzene	ND	5.0	19	*	11	H	19	н	
Chloroethane	ND	5.0	18	n	11	n	h	н	
Chloroform	ND	5.0	Ħ	0	н	H	ŧı	র	
Chloromethane	ND	5.0	10	н	tt	**	44	Ħ	
2-Chlorotoluene	ND	5.0	#	•	н	п	4	11	
4-Chlorotoluene	ND	5.0	19	и	W	41	11	D	
Dibromochloromethane	ND	5.0	н	11	11	11	и	и	
1,2-Dibromo-3-chloropropane	ND	5.0		u	н	н	#	#1	
1,2-Dibromoethane (EDB)	ND	5.0	п	4	+t	16	м	н	
Dibromomethane	ND	5.0	"	11	н	n	o o	11	
1,2-Dichlorobenzene	ND	5.0	н	h	н	n	11	15	
1,3-Dichlorobenzene	ND	5.0	11	91	tt	0	н	и	
1,4-Dichlorobenzene	ND	5.0		н	11	29	11	ы	
Dichlorodifluoromethane	ND	5.0	0	11	11	"	н	н	
1,1-Dichloroethane	ND	5.0	16	п	н	n	- 0	#	
1,2-Dichloroethane	ND	5.0	п	н	11	*	n	18	
1.1-Dichloroethene	ND	5.0	71	Ħ	н	н	0	11	
cis-1,2-Dichloroethene	ND	5.0	н	,	u	tt	11	"	
trans-1,2-Dichloroethene	ND	5.0	12	41	16	13	н	e	
1,2-Dichloropropane	ND	5.0	11	ts	н	н	н	at .	
1,3-Dichloropropane	ND ND	5.0	79	t)	41	11	н	#	
2,2-Dichloropropane	ND ND	5.0		**	м	н	er	11	
	ND ND	5.0		н	ŧr	н	v	н	
1,1-Dichloropropene		5.0		ŧī	11	17	в	B	
cis-1,3-Dichloropropene	ND ND	5.0 5.0		н	11	н	Ħ	11	
trans-1,3-Dichloropropene				11	16	17	н	tf.	
Hexachlorobutadiene	ND	5.0		"	н		H	я.	
Isopropylbenzene	ND	5.0		15	.,	н	:i	**	
p-Isopropyltoluene	ND	5.0		11	#	te	ч	" fi	
Methylene chloride	ND	5.0		11	n	f! H	11	**	
Naphthalene	ND	5.0		и	,	н	11	H	
n-Propylbenzene	ND	5.0		н	1)	н	11	н	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Targas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 16:42

S5-6'' T701524-01 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Volatile Organic Compounds by E	PA Method 82601	3							
Styrene	ND	5.0	ug/kg	1	7112717	11/27/07	11/30/07	EPA 8260B	
1,1,2,2-Tetrachloroethane	ND	5.0	15	11	11	44	н	н	
1,1,1,2-Tetrachloroethane	ND	5.0	19	н	18	н	91	11	
Tetrachloroethene	ND	5.0	17	Ħ	н	n	11	н	
1,2,3-Trichlorobenzene	ND	5.0	**	11	**	**	**	и	
1,2,4-Trichlorobenzene	ND	5.0	11	11	н	н	11	н	
1,1,2-Trichloroethane	ND	5.0	1#	u	*1		н	н	
1,1,1-Trichloroethane	ND	5.0	n	π	11	11	н	н	
Trichloroethene	ND	5.0	n	n	n	n	11	11	
Trichlorofluoromethane	ND	5.0	.,	11	M	н	п	it	
1,2,3-Trichloropropane	ND	5.0	11	114	, H	#1	н	n	
1,3,5-Trimethylbenzene	ND	5.0	н	n	4	ti	11	u	
1,2,4-Trimethylbenzene	ND	5.0	11	11	н	11	н	H	
Vinyl chloride	ND	5.0	II.	н	11	**	u u	ti	
Benzene	ND	5.0	11	N	n	h	11	If	
Toluene	ND	5.0	11	tr	n	Ħ	H	n	
Ethylbenzene	ND	5.0		11	н	11	н	n n	
m,p-Xylene	ND	5.0	19	n	11	41	0	#	
o-Xylene	ND	5.0	+1	91	13	н	13	н	
C6-C12 (GRO)	ND	500	Ħ	п	it	н	ŧΤ	н	
Surrogate: 4-Bromofluorobenzene		88.6 %	81	-118	"	"	21	u	
Surrogate: Dibromofluoromethane		99.2 %	73	-127	"	"	"	"	
Surrogate: Toluene-d8		96.9 %	85	-115	11	"	n	"	
Jan . John Lowelle wo									

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tayos

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 16:42

S6-6'' T701524-03 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Extractable Petroleum Hydrocarbons by 8	015B								
C6-C12 (GRO)	ND	0.10	mg/kg	1	7112714	11/27/07	11/27/07	EPA 8015B	
C13-C28 (DRO)	36	0.10	n	ĸ	н	v	н	н	
C29-C40 (MORO)	240	0.10	11	11	Ħ	n	11-	15	
Surrogate: p-Terphenyl		103 %	65	135	"	n	"	н	
Metals by EPA 6010B									
Antimony	ND	3.0	mg/kg	1	7112808	11/28/07	12/05/07	EPA 6010B	
Silver	ND	2.0	#1	1t	Ħ	н	15	н	
Arsenie	ND	5.0	19	bj	ŧŧ	0	15	ก	
Barium	140	1.0	15	11	31	17	н	и	
Beryllium	ND	1.0	U	н	11	0	н	11	
Cadmium	ND	2.0	f +	15	15	Ħ	rc	н	
Chromium	41	2.0	5)	н	0	н	All	11	
Cobalt	11	2.0	1)	ŧi	H	н	łt	н	
Copper	22	1.0	51	и	46	н	er .	11	
Lead	21	3.0	11	n	11	и	1t	*	
Molybdenum	ND	1.0	п	н	11	11	м	Ъ	
Nickel	18	2.0	11	11	н	0	H	19	
Selenium	ND	5.0	112	н	11	Ħ	n	rt	
Thallium	ND	2.0	19	11	н	н	11	н	
Vanadium	60	5.0	16	"	11	H	11	H	
Zinc	93	1.0	n	11	н	u	H	15	
Cold Vapor Extraction EPA 7470/7471									
Mercury	ND	0.10	mg/kg	1	7112809	11/28/07	11/30/07	EPA 7471A Soil	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tagas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 16:42

S6-6" T701524-03 (Soil)

Analyte R	esult	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	borator	ies, Inc.					
Volatile Organic Compounds by EPA Metho	od 8260	В							
Styrene	ND	5.0	ug/kg	1	7112717	11/27/07	11/30/07	EPA 8260B	
1,1,2,2-Tetrachloroethane	ND	5.0	11	н	98	**	Ħ	16	
1,1,1,2-Tetrachloroethane	ND	5.0	11	11	н	н	11	М	
Tetrachloroethene	ND	5.0	н	v	н	τŧ	- tt	st	
1,2,3-Trichlorobenzene	ND	5.0	19	11	n	H	n	115	
1,2,4-Trichlorobenzene	ND	5.0	17	n	tı	н	n	н	
1,1,2-Trichloroethane	ND	5.0	16	u	н	Ħ	**	н	
1,1,1-Trichloroethane	ND	5.0	11	н	47	O	tį	n.	
Trichloroethene	ND	5.0	Ħ	н	19	şı	łſ	11	
Trichlorofluoromethane	ND	5.0	15	et	н	- 10	17	я	
1,2,3-Trichloropropane	ND	5.0	11	0	Ħ	11	v	н	
1,3,5-Trimethylbenzene	ND	5.0	11	**	"	n	н	41	
1,2,4-Trimethylbenzene	ND	5.0	†I	11	Ħ	н	ĸ	41	
Vinyl chloride	ND	5.0	†1	11	н	н	Ħ	Ħ	
Benzene	ND	5.0	,,	н	11	1)	tr	19	
Toluene	ND	5.0	11	н	10	0	ų	19	
Ethylbenzene	ND	5.0	11	tt.	' н	tt	17	п	
m,p-Xylene	ND	5.0	ท	ŧI	п	0	v	R	
o-Xylene	ND	5.0	*1	**	n .	n n	ts	85	
C6-C12 (GRO)	ND	500	17	11	H	н	Ŋ	11	
Surrogate: 4-Bromofluorobenzene		93.5 %	81	-118	25	11	tt	tt	
Surrogate: Dibromofluoromethane		97.6 %	73	-127	n	n	"	"	
Surrogate: Toluene-d8		98.9 %	85	-115	"	"	"	"	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Targas

4730 Palm Avenue, Suite 213

Project: Al's Corner

Project Number: [none]

Reported: 12/10/07 16:42

La Mesa CA, 91941

Project Manager: Brian Brennan

\$7-6'' T701524-05 (Soil)

Analyte R	esult	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	borator	ies, Inc.					
Extractable Petroleum Hydrocarbons by 80:	15B								
C6-C12 (GRO)	27	0.10	mg/kg	1	7112714	11/27/07	11/27/07	EPA 8015B	
C13-C28 (DRO)	52	0.10	11	11	41	n	*1	n	
C29-C40 (MORO)	160	0.10	19	41	tt	H	н	В	
Surrogate: p-Terphenyl		111 %	65	135	**	"	n	#	
Metals by EPA 6010B									
Antimony	ND	3.0	mg/kg	1	7112808	11/28/07	12/05/07	EPA 6010B	
Silver	ND	2.0	13	n	11	н	et et	11	
Arsenic	ND	5.0	"	н	n	a	17	н	
Barium	140	1.0	Ħ	н	н	tt	15	19	
Beryllium	ND	1.0	11	q	н	11	D	n	
Cadmium	ND	2.0	11	**	н	0	tt	H	
Chromium	40	2.0	19	17	11	n	41	**	
Cobalt	11	2.0	9	Ħ	н	н	n	н	
Copper	25	1.0	п	15	11	NI .	11	η	
Lead	29	3.0	†1	it	91	Ħ	n	N	
Molybdenum	ND	1.0	11	н	11	n	11	11	
Nickel	15	2.0	11	11	"	n	n	н	
Selenium	ND	5.0	11	п	н	n	11	17	
Thallium	ND	2.0	11	n	15	n	11	н	
Vanadium	54	5.0	31	n	н	п	n	U	
Zinc	150	1.0	11	0	11	н	17	**	
Cold Vapor Extraction EPA 7470/7471									
Mercury	ND	0.10	mg/kg	1	7112809	11/28/07	11/30/07	EPA 7471A Soil	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 16:42

S7-6" T701524-05 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Note
		SunStar La	aborato	ries, Inc.					
Volatile Organic Compounds by I	EPA Method 826	0B							
Bromobenzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/30/07	EPA 8260B	
Bromochloromethane	ND	5.0	**	н	н	11	н	n	
Bromodichloromethane	ND	5.0	н	1f	ŧl	n	41	Ħ	
Bromoform	ND	5.0		71	11	tf	16	IF	
Bromomethane	ND	5.0	11	rt	ti .	11	n	н	
n-Butylbenzene	ND	5.0	17	н	н	15	н	11	
sec-Butylbenzene	ND	5.0	н	11	11	н	11	17	
tert-Butylbenzene	ND	5.0	14	н	н	-tt	н	н	
Carbon tetrachloride	ND	5.0	n	11	41	н	11	11	
Chlorobenzene	ND	5.0	"	t)	11	Ħ	11	N	
Chloroethane	ND	5.0	19	п	п	31	М	Ħ	
Chloroform	ND	5.0	н	u	41	n	4	st	
Chloromethane	ND	5.0	##	Ħ	tt	н	н	37	
2-Chlorotoluene	ND	5.0	15	11	**	h	15	"	
4-Chlorotoluene	ND	5.0	11	п	н	11	"	D	
Dibromochloromethane	ND	5.0	19	11	17	n	71	**	
1,2-Dibromo-3-chloropropane	ND	5.0	п	н	н	а	ŧŧ	n	
1,2-Dibromoethane (EDB)	ND	5.0	**	н	**	11	**	ч	
Dibromomethane	ND	5.0	**	(1	11	н	11	н	
1,2-Dichlorobenzene	ND	5.0	n	н	н	0	н	11	
1,3-Dichlorobenzene	ND	5.0	13	**	n	н	47	я	
1,4-Dichlorobenzene	ND	5.0	н	"	н	11	п	11	
Dichlorodifluoromethane	ND	5.0	13	n	11	n	11	**	
	ND	5.0	15	н	н	τŧ	ıı	19	
1,1-Dichloroethane	ND	5.0		33	11	tf	rt	59	
1,2-Dichloroethane	ND	5.0		н	н	16	н	#	
1,1-Dichloroethene	ND ND	5.0		н	н	11	м	n	
cis-1,2-Dichloroethene	ND ND	5.0		*17	u.	n	11	n	
trans-1,2-Dichloroethene		5.0		н	н	11	н	ч	
1,2-Dichloropropane	ND	5.0		Ħ	tr	н		H	
1,3-Dichloropropane	ND	5.0		,,	u	**	**	11	
2,2-Dichloropropane	ND	5.0 5.0		1)	11	41	н	в	
1,1-Dichloropropene	ND			н	н	16	N	11	
cis-1,3-Dichloropropene	ND	5.0	ļi	4	1	н	TE	H	
trans-1,3-Dichloropropene	ND	5.0	,	,,	e e	,	41	н	
Hexachlorobutadiene	ND	5.0	,	и.	n .		н	R	
Isopropylbenzene	ND	5.0	,	rt s1		н	r.	#	
p-Isopropyltoluene	14	5.0	,	#1 #E	18	н	16	ps.	
Methylene chloride	ND	5.0	,		11	н	15	н.	
Naphthalene	ND	5.0		18					
n-Propylbenzene	ND	5.0) "	н	н	11	н	"	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Targas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 16:42

\$7-6'' T701524-05 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	borator	ies, Inc.					
Volatile Organic Compounds by E	PA Method 8260	В							
Styrene	ND	5.0	ug/kg	1	7112717	11/27/07	11/30/07	EPA 8260B	
1,1,2,2-Tetrachloroethane	ND	5.0	15	n	н	11.	n	n	
1,1,1,2-Tetrachloroethane	ND	5.0	11	н	n	17	#	IF	
Tetrachloroethene	ND	5.0	ıf	H	H	44	19	n	
1,2,3-Trichlorobenzene	ND	5.0	19	11	11	Ħ	11	31	
1,2,4-Trichlorobenzene	ND	5.0	79	н	н	11	**	p	
1,1,2-Trichloroethane	ND	5.0	**	и.	11	,,	11-	ıı	
1,1,1-Trichloroethane	ND	5.0	17	41	19	n	11	1f	
Trichloroethene	ND	5.0	11	11	**	н	4	11	
Trichlorofluoromethane	ND	5.0	"	tt	u	11	а	tt	
1,2,3-Trichloropropane	ND	5.0	37	"	18	n	45	#	
1,3,5-Trimethylbenzene	ND	5.0	11	11	41	n	11	ff.	
1,2,4-Trimethylbenzene	ND	5.0	19	q	ŧŧ	к	4	41	
Vinyl chloride	ND	5.0	19	n	£1	N	н	o	
Benzene	ND	5.0	19	н	н	†t	п	ts.	
Toluene	ND	5.0	H	н	н	46	ıs	n	
Ethylbenzene	ND	5.0	7)	**	Ħ	н	п	н	
m,p-Xylene	ND	5.0	71	. "	н	0	н	п	
o-Xylene	ND	5.0	n	н	м	44	ř.	n	
C6-C12 (GRO)	ND	500	ŦI	н	N	11	ļt.	H	
Surrogate: 4-Bromofluorobenzene		88.8 %	81	-118	"	11	11	и	
Surrogate: Dibromofluoromethane		96,4 %	73	-127	"	17	**	"	
Surrogate: Toluene-d8		95.6 %		-115	17	11	n	n	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tangas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 16:42

Extractable Petroleum Hydrocarbons by 8015B - Quality Control SunStar Laboratories, Inc.

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 7112714 - EPA 3550B GC					<u> </u>	······································				
Blank (7112714-BLK1)				Prepared	& Analyz	ed: 11/27/	07			
Surrogate: p-Terphenyl	92.4		mg/kg	100		92.4	65-135			
C13-C28 (DRO)	ND	0.10	tt							
LCS (7112714-BS1)				Prepared	& Analyz	ed: 11/27/	07		-2-	
Surrogate: p-Terphenyl	94.7		mg/kg	100		94.7	65-135			
C13-C28 (DRO)	470	0.10	11	500		93.7	75-125			
Matrix Spike (7112714-MS1)	So	urce: T70152	21-01	Prepared:	11/27/07	Analyzec	l: 11/28/07			
Surrogate: p-Terphenyl	106		mg/kg	100		106	65-135			
C13-C28 (DRO)	490	0.10	IF	500	ND	97.5	75-125			
Matrix Spike Dup (7112714-MSD1)	So	urce: T70152	21-01	Prepared:	: 11/27/07	Analyzed	l: 11/28/07			
Surrogate: p-Terphenyl	108		mg/kg	100	****	108	65-135			
C13-C28 (DRO)	580	0.10	11	500	ND	116	75-125	16.9	20	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Albert Vargas, Project Coordinator

aller Tangas

Page 11 of 18

4730 Palm Avenue, Suite 213

Project: Al's Corner

Project Number: [none]

Reporting

Reported: 12/10/07 16:42

RPD

%REC

La Mesa CA, 91941

Project Manager: Brian Brennan

Metals by EPA 6010B - Quality Control SunStar Laboratories, Inc.

Spike

Source

Antimony Ant	Analyte	Result	Kepornng Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Prepared: 11/28/07 Analyzed: 12/03/07	Batch 7112808 - EPA 3051					···					
ND 2.0 " NSENICE ND 5.0 " NSENICE ND 5.0 " ND 1.0 " ND 1.	Blank (7112808-BLK1)				Prepared:	11/28/07	Analyzed	l: 12/03/07			
Nomeric ND 5.0 " Sarium ND 1.0 " Serythium ND 1.0 " Cadmium ND 2.0 " Chromium ND 3.0	Antimony	ND	3.0	mg/kg							
NB 1.0 " Seryllium ND 1.0 " Seryllium ND 1.0 " Cadmium ND 2.0 " Chromium ND 3.0 " Chromium ND 3.0 " Chromium ND 3.0 " Chromium ND 3.0 " Chromium ND 1.0 " Chromium ND 5.0 " Chromium ND 5.0 " Chromium ND 5.0 " Chromium ND 1.0 " Ch	Silver	ND	2.0	B							
Sarulm ND 1.0	Arsenic	ND	5.0	18							
ND	Barium	ND	1.0	ti							
Agriculum	Beryllium	ND	1.0	41							
Cobalt	Cadmium	ND	2.0	Ht							
ND	Chromium	ND	2.0	II							
Appen ND 1.0	Cobalt	ND	2.0	H							
Molybdenum ND 1.0 " ND 2.0 " ND 5.0 " Thallium ND 5.0 " Thallium ND 5.0 " ND 1.0 " Thallium ND 5.0 " ND 1.0 " N	Copper	ND	1.0	11							
ND 1.0 ND 2.0	Lead	ND	3.0	It							
ND	Molybdenum	ND	1.0	if							
ND 2.0	Nickel	ND	2.0	IE							
Vanadium	Selenium	ND	5.0	tt							
ND	Thallium	ND	2.0	н							
Prepared: 11/28/07 Analyzed: 12/03/07	Vanadium	ND	5.0	tt							
Arsenic 118 5.0 mg/kg 100 118 75-125 Barium 113 1.0 " 100 113 75-125 Cadmium 112 2.0 " 100 112 75-125 Chromium 112 2.0 " 100 112 75-125 Lead 111 3.0 " 100 111 75-125 Matrix Spike (7112808-MS1) Source: T701520-01 Prepared: 11/28/07 Analyzed: 12/03/07 QM-Arsenic 90.4 5.0 mg/kg 100 ND 90.4 75-125 Barium 278 1.0 " 100 233 45.6 75-125 Cadmium 86.3 2.0 " 100 4.80 81.5 75-125 Chromium 185 2.0 " 100 282 NR 75-125 QM-Cadmium 185 2.0 " 100 282 NR 75-125	Zinc	ND	1.0	B							
Barium 113 1.0 " 100 113 75-125 Cadmium 112 2.0 " 100 112 75-125 Chromium 112 2.0 " 100 112 75-125 Lead 111 3.0 " 100 111 75-125 Matrix Spike (7112808-MS1) Source: T701520-01 Prepared: 11/28/07 Analyzed: 12/03/07 QM- Arsenic 90.4 5.0 mg/kg 100 ND 90.4 75-125 Barium 278 1.0 " 100 233 45.6 75-125 QM- Cadmium 86.3 2.0 " 100 4.80 81.5 75-125 QM- Chromium 185 2.0 " 100 282 NR 75-125 QM-	LCS (7112808-BS1)				Prepared	: 11/28/07		d: 12/03/07	· 		
Cadmium 112 2.0 " 100 112 75-125 Chromium 112 2.0 " 100 112 75-125 Lead 111 3.0 " 100 111 75-125 Matrix Spike (7112808-MS1) Source: T701520-01 Prepared: 11/28/07 Analyzed: 12/03/07 QM- Arsenic 90.4 5.0 mg/kg 100 ND 90.4 75-125 Barium 278 1.0 " 100 233 45.6 75-125 QM- Cadmium 86.3 2.0 " 100 4.80 81.5 75-125 QM- Chromium 185 2.0 " 100 282 NR 75-125 QM-	Arsenic	118	5.0	mg/kg	100		118	75-125			
Chromium 112 2.0 " 100 112 75-125 Lead 111 3.0 " 100 111 75-125 Matrix Spike (7112808-MS1) Source: T701520-01 Prepared: 11/28/07 Analyzed: 12/03/07 QM-Arsenic 90.4 5.0 mg/kg 100 ND 90.4 75-125 Barium 278 1.0 " 100 233 45.6 75-125 QM-Cadmium 86.3 2.0 " 100 4.80 81.5 75-125 Chromium 185 2.0 " 100 282 NR 75-125 QM-	Barium	113	1.0	Ħ	100		113	75-125			
Lead 111 3.0 " 100 111 75-125 Matrix Spike (7112808-MS1) Source: T701520-01 Prepared: 11/28/07 Analyzed: 12/03/07 QM- Arsenic 90.4 5.0 mg/kg 100 ND 90.4 75-125 Barium 278 1.0 " 100 233 45.6 75-125 QM- Cadmium 86.3 2.0 " 100 4.80 81.5 75-125 QM- Chromium 185 2.0 " 100 282 NR 75-125 QM-	Cadmium	112	2.0	EF	100		112	75-125			
Matrix Spike (7112808-MS1) Source: T701520-01 Prepared: 11/28/07 Analyzed: 12/03/07 QM-0 Arsenic 90.4 5.0 mg/kg 100 ND 90.4 75-125 Barium 278 1.0 " 100 233 45.6 75-125 QM-0 Cadmium 86.3 2.0 " 100 4.80 81.5 75-125 QM-0 Chromium 185 2.0 " 100 282 NR 75-125 QM-0	Chromium	112	2.0	11	100		112	75-125			
Arsenic 90.4 5.0 mg/kg 100 ND 90.4 75-125 Barium 278 1.0 " 100 233 45.6 75-125 QM- Cadmium 86.3 2.0 " 100 4.80 81.5 75-125 Chromium 185 2.0 " 100 282 NR 75-125 QM-	Lead	111	3.0	tt	100		111	75-125			
Arsenic 90.4 5.0 mg/kg 100 ND 90.4 75-125 Barium 278 1.0 " 100 233 45.6 75-125 QM-Cadmium Cadmium 86.3 2.0 " 100 4.80 81.5 75-125 T5-125 Chromium 185 2.0 " 100 282 NR 75-125 QM-	Matrix Spike (7112808-MS1)	Sc	ource: T7015	20-01	Prepared	: 11/28/07	7 Analyze	d: 12/03/07	7		QM-07
Cadmium 86.3 2.0 " 100 4.80 81.5 75-125 Chromium 185 2.0 " 100 282 NR 75-125 QM-	Arsenic	90.4	5.0	mg/kg	100	ND	90.4	75-125			
Chromium 185 2.0 " 100 282 NR 75-125 QM-	Barium	278	1.0	tt	100	233	45.6	75-125			QM-07
Chroman	Cadmium	86.3	2.0	H	100	4.80	81.5	75-125			
01/	Chromium	185	2.0	u	100	282	NR	75-125			QM-0
	Lead	775	3.0	u	100	954	NR	75-125			QM-0

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tayons

Analyte

4730 Palm Avenue, Suite 213 La Mesa CA, 91941

Project Number: [none]

Reporting

Limit

Result

Project Manager: Brian Brennan

Reported: 12/10/07 16:42

RPD

Limit

Notes

Metals by EPA 6010B - Quality Control

Project: Al's Corner

SunStar Laboratories, Inc.

Spike

Level

Source

Result

%REC

Limits

RPD

%REC

Batch 7112808 - EPA 3051										
Matrix Spike Dup (7112808-MSD1)	Sourc	e: T70152	20-01	Prepared:	11/28/07	Analyze	1: 12/03/07			QM-07
Arsenic	105	5.0	mg/kg	100	ND	105	75-125	15.1	20	
Barium	354	1.0	It	100	233	121	75-125	23.9	20	QM-07
Cadmium	97.3	2.0	Ħ	100	4.80	92.5	75-125	12.0	20	
Chromium	179	2.0	11	100	282	NR	75-125	3.32	20	QM-07
Lead	1020	3.0	Ħ	100	954	60.8	75-125	26.8	20	QM-07

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tagas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 16:42

Volatile Organic Compounds by EPA Method 8260B - Quality Control SunStar Laboratories, Inc.

										1
	Ŧ	Reporting		Spike	Source		%REC		RPD	1
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes

Batch	7112717 -	EPA 5030	GCMS

Blank (7112717-BLK1)				Prepared: 11/2	27/07 Analyzed	1: 11/29/07	
Surrogate: 4-Bromofluorobenzene	7.26		ug/kg	8.00	90.8	81-118	 -,,,
Surrogate: Dibromofluoromethane	8.68		"	8.00	108	73-127	
Surrogate: Toluene-d8	8.25		"	8.00	103	85-115	
Bromobenzene	ND	5.0	"				
Bromochloromethane	ND	5.0	IF.				
Bromodichloromethane	ND	5.0	4f				
Bromoform	ND	5.0	и			•	
Bromomethane	ND	5.0	rt.				
n-Butylbenzene	ND	5.0	It				
sec-Butylbenzene	ND	5.0	11				
tert-Butylbenzene	ND	5.0	Ħ				
Carbon tetrachloride	ND	5.0	IF				
Chlorobenzene	ND	5.0	11				
Chloroethane	ND	5.0	0				
Chloroform	ND	5.0	11				
Chloromethane	ND	5.0	ti				
2-Chlorotoluene	ND	5.0	н				
4-Chlorotoluene	ND	5.0	31				
Dibromochloromethane	ND	5.0	n				
1,2-Dibromo-3-chloropropane	ND	5.0	II.				
1,2-Dibromoethane (EDB)	ND	5.0	u				
Dibromomethane	ND	5.0	u				
1,2-Dichlorobenzene	ND	5.0	it				
1,3-Dichlorobenzene	ND	5.0	H.				
1,4-Dichlorobenzene	ND	5.0	н				
Dichlorodifluoromethane	ND	5.0	H				
1,1-Dichloroethane	ND	5.0	11				
1,2-Dichloroethane	ND	5.0	11				
1,1-Dichloroethene	ND	5.0	Ħ				
cis-1,2-Dichloroethene	ND	5.0	Ħ				
trans-1,2-Dichloroethene	ND	5.0	II.				
1,2-Dichloropropane	ND	5.0	я				
1,3-Dichloropropane	ND	5.0	и				
2,2-Dichloropropane	ND	5.0	Ш				
1,1-Dichloropropene	ND	5.0	11				
cis-1,3-Dichloropropene	ND	5.0	Ð				
trans-1,3-Dichloropropene	ND	5.0	It				
Hexachlorobutadiene	ND	5.0	11				
Isopropylbenzene	ND	5.0	tt .				
p-Isopropyitoluene	ND	5.0	II				
Methylene chloride	ND	5.0	ŧi				

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

Analyte

4730 Palm Avenue, Suite 213

Project: Al's Corner

Project Number: [none] Project Manager: Brian Brennan

Units

Reported: 12/10/07 16:42

RPD

Limit

Notes

RPD

%REC

Limits

La Mesa CA, 91941

Volatile Organic Compounds by EPA Method 8260B - Quality Control

Spike

Level

Source

Result

%REC

SunStar Laboratories, Inc.

Reporting

Limit

Result

Blank (7112717-BLK1)				Prepared: 11/2	7/07 Analyzed	: 11/29/07
Vaphthalene	ND	5.0	ug/kg			
-Propylbenzene	ND	5.0	11			
Styrene	ND	5.0	Ħ			
,1,2,2-Tetrachloroethane	ND	5.0	II.			
,1,1,2-Tetrachloroethane	ND	5.0	Ш			
letrachloroethene	ND	5.0	н			
,2,3-Trichlorobenzene	ND	5.0	IT			
,2,4-Trichlorobenzene	ND	5.0	11			•
,1,2-Trichloroethane	ND	5.0	В			
1,1,1-Trichloroethane	ND	5.0	н			•
Frichloroethene	ND	5.0	п			
Prichlorofluoromethane	ND	5.0	EQ.			
1,2,3-Trichloropropane	ND	5.0	H			
1,3,5-Trimethylbenzene	ND	5.0	31			
1,2,4-Trimethylbenzene	ND	5.0	ы			
Vinyl chloride	ND	5.0	я			
Benzene	ND	5.0	11			
Toluene	ND	5.0	Ħ			
Ethylbenzene	ND	5.0	tt			
m,p-Xylene	ND	5.0	It			
o-Xylene	ND	5.0	11			
C6-C12 (GRO)	ND	500	je			
LCS (7112717-BS1)				Prepared: 11/2	27/07 Analyzed	1: 12/01/07
Surrogate: 4-Bromofluorobenzene	8.11		ug/kg	8.00	101	81-118
Surrogate: Dibromofluoromethane	7.98		ır	8.00	99.8	73-127
Surrogate: Toluene-d8	7.96		tt.	8.00	99.5	85-115
Chlorobenzene	91.7	5.0	ы	100	91.7	75-125
I,1-Dichloroethene	97.2	5.0	u	100	97.2	75-125
Trichloroethene	97.4	5.0	#1	100	97.4	75-125
Benzene	93.0	5.0	а	100	93.0	75-125
Toluene	91.9	5.0	n	100	91.9	75-125

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tayon

Analyte

4730 Palm Avenue, Suite 213

Project: Al's Corner

Project Number: [none] Project Manager: Brian Brennan

Reported: 12/10/07 16:42

RPD

Limit

Notes

RPD

%REC

Limits

La Mesa CA, 91941

Volatile Organic Compounds by EPA Method 8260B - Quality Control

Source

Result

%REC

Spike

Level

SunStar Laboratories, Inc.

Units

Reporting

Result

Limit

Matrix Spike (7112717-MS1)	Sourc	e: T70152	3-03	Prepared:	11/27/07	Analyzed:	12/01/07			
Surrogate: 4-Bromofluorobenzene	7.87		ug/kg	8.00		98.4	81-118			
Surrogate: Dibromofluoromethane	7.89		11	8.00		98.6	73-127			
Surrogate: Toluene-d8	8.03		"	8.00		100	85-115			
Chlorobenzene	61.2	5.0	13	100	ND	61.2	75-125			QM-07
I,1-Dichloroethene	78.4	5.0	n	100	ND	78.4	75-125			
Trichloroethene	70.0	5.0	H	100	ND	70.0	75-125			QM-07
Benzene	74.3	5.0	11	100	ND	74.3	75-125			QM-07
Toluene	63.6	5.0	àl	100	ND	63.6	75-125			QM-07
Matrix Spike Dup (7112717-MSD1)	Source	ce: T70152	3-03	Prepared:	11/27/07	Analyzed:	12/01/07			
Surrogate: 4-Bromofluorobenzene	7.94		ug/kg	8.00		99.2	81-118			
Surrogate: Dibromofluoromethane	7.42		29	8.00		92.8	73-127			
Surrogate: Toluene-d8	7.92		21	8.00		99.0	85-115			
Chlorobenzene	60.8	5.0	l)	100	ND	60.8	75-125	0.737	20	QM-07
1,1-Dichloroethene	50.5	5.0	11	100	ND	50.5	75-125	43.2	20	QM-07 QR-02
Trichloroethene	58.4	5.0	li.	100	ND	58.4	75-125	17.9	20	QM-07
Benzene	63.3	5.0	1)	100	ND	63.3	75-125	16.0	20	QM-01
	56.2	5.0	п	100	ND	56.2	75-125	12,3	20	QM-01

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Waryon

Project: Al's Corner

4730 Palm Avenue, Suite 213

Project Number: [none]

Reported:

La Mesa CA, 91941

Project Manager: Brian Brennan

12/10/07 16:42

Notes and Definitions

QR-02

The RPD result exceeded the QC control limits; however, both percent recoveries were acceptable. Sample results for the QC

batch were accepted based on percent recoveries and completeness of QC data.

QM-07

The spike recovery and or RPD was outside acceptance limits for the MS and/or MSD. The batch was accepted based on

acceptable LCS recovery.

DET

Analyte DETECTED

ND

Analyte NOT DETECTED at or above the reporting limit

NR

Not Reported

dry

Sample results reported on a dry weight basis

RPD

Relative Percent Difference

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tagas

Received good condition(court & C

Seals intact? Y/N(RED

Date / Time

Received by

Date /

40/121

=

Total # of containers

Date / Time

(200 Chain of Custody seals YINMA

Chain of Custody Record

SunStar Laboratories, Inc. 3002 Dow Ave., Ste. 212

Tustin, CA 92780

714-505-4010

Address: Client:

Project Manager: Phone: [[//

Cliant Project #: CM - 704 Project Name: Collector

Batch #:

COC 71373

CisclO nochsOlix3 M8108 > (laseib) Mčr08 (enilossg) M2r08 8021 BTEX

Total # of containers

Comments/Preservative

Laboratory ID #

elisieM. SS etiiT 000T\0108

0/25 8260 BTEX, OXY only 4XO + 0929

9560

Container

Sample

Time

Date Sampled

Sample ID

00

Date / Time /

Relinquished by: (signature)

Relinquished by: (signature)

Sample disposal Instructions: Disposal @ \$2.00 each

Return to cilent

Received by: (signature)

Date / Time

Pickup

Date / Time

Turn around time:

10 December 2007

Brian Brennan EEI - La Mesa 4730 Palm Avenue, Suite 213 La Mesa, CA 91941

aller Varyas

RE: Al's Corner

Enclosed are the results of analyses for samples received by the laboratory on 11/21/07 12:00. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Albert Vargas

Project Coordinator

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

ANALYTICAL REPORT FOR SAMPLES

Sample ID	Laboratory ID	Matrix	Date Sampled	Date Received
B1-5	T701523-01	Soil	11/20/07 09:15	11/21/07 12:00
B1-10	T701523-02	Soil	11/20/07 09:20	11/21/07 12:00
B1-15	T701523-03	Soil	11/20/07 09:35	11/21/07 12:00
B2-5	T701523-07	Soil	11/20/07 10:40	11/21/07 12:00
B3-5	T701523-11	Soil	11/20/07 12:40	11/21/07 12:00
B3-10	T701523-12	Soil	11/20/07 12:45	11/21/07 12:00
B3-15	T701523-13	Soil	11/20/07 12:50	11/21/07 12:00
B4-5	T701523-17	Soil	11/20/07 13:45	11/21/07 12:00
B4-10	T701523-18	Soil	11/20/07 13:50	11/21/07 12:00
B4-15	T701523-19	Soil	11/20/07 14:00	11/21/07 12:00
B5-5	T701523-23	Soil	11/21/07 09:55	11/21/07 12:00
B6-5	T701523-26	Soil	11/21/07 10:25	11/21/07 12:00
B6-10	T701523-27	Soil	11/21/07 10:30	11/21/07 12:00
B6-15	T701523-28	Soil	11/21/07 10:40	11/21/07 12:00
B7-5	T701523-30	Soil	11/21/07 10:55	11/21/07 12:00
B7-10	T701523-31	Soil	11/21/07 11:00	11/21/07 12:00
B7-15	T701523-32	Soil	11/21/07 11:05	11/21/07 12:00

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

4730 Palm Avenue, Suite 213 La Mesa CA, 91941 Project: Al's Corner

Project Number: [none]

Reported: 12/10/07 17:03

Project Manager: Brian Brennan

B1-5 T701523-01 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
No. of the control of		SunStar La	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead	5.6	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by EPA	Method 8260	B							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	ŧŧ	n	ĸ	17	н	11	
Ethylbenzene	ND	5.0	11	н	11	tt	n	я	
m,p-Xylene	ND	5.0	11	H	11	н	Ħ	н	
o-Xylene	ND	5.0	11	н	v	н	10	м	
Methyl tert-butyl ether	ND	20	н	+1	e1	14	•	H	
C6-C12 (GRO)	ND	500	15		Jt .	1)	\$ †	11	
Surrogate: 4-Bromofluorobenzene		92.6 %	81-	118	11	"	"	n	
Surrogate: Dibromofluoromethane		109 %	73-	127	"	Ħ	***	ш	
Surrogate: Toluene-d8		103 %	85-	115	"	"	28	11	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Targas

4730 Palm Avenue, Suite 213 La Mesa CA, 91941 Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B1-10 T701523-02 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead	6.2	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by El	PA Method 8260)B							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	17	41	17	0	11	11	
Ethylbenzene	ND	5.0	19	n	ч	11	1)	ŧŧ	
m,p-Xylene	ND	5.0	Ħ	15	Ţί	н	п	Ħ	
o-Xylene	ND	5.0	11	11	17	16	11	Ħ	
Methyl tert-butyl ether	ND	20	n	11	11	11	11	Ħ	
C6-C12 (GRO)	ND	500	"	п	11	н	н	н	
Surrogate: 4-Bromofluorobenzene		91.6 %	81-	118	"	н	n	"	
Surrogate: Dibromofluoromethane		111 %	73-	127	"	"	"	n .	
Surrogate: Toluene-d8		102 %	85-	115	и	"	#	i.	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Trangas

4730 Palm Avenue, Suite 213 La Mesa CA, 91941 Project: Al's Corner

Project Number: [none]
Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B1-15 T701523-03 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead	4.0	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by E	PA Method 8260	В							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	19	44	11	н	11	51	
Ethylbenzene	ND	5.0	**	11	11	n	11	Ħ	
m,p-Xylene	ND	5.0	53	0	н	n	41	и	
o-Xylene	ND	5.0	11	10	1)	n	16	11-	
Methyl tert-butyl ether	ND	20	tt	n	v	н	11	11	
C6-C12 (GRO)	ND	500	15	11	(1	H	11	11	
Surrogate: 4-Bromofluorobenzene		92.4 %	81-	118	"	п	н	n	
Surrogate: Dibromofluoromethane		117 %	<i>73</i> -	127	11	н	"	u	
Surrogate: Toluene-d8		104 %	85-	115	11	#	"	tt.	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Targas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B2-5 T701523-07 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Extractable Petroleum Hydrocarbons by	8015B								
C6-C12 (GRO)	ND	0.10	mg/kg	1	7112714	11/27/07	11/27/07	EPA 8015B	
C13-C28 (DRO)	ND	0.10	13	11	н	0	n	11	
C29-C40 (MORO)	ND	0.10	11	я	12	н	Ħ	if	
Surrogate: p-Terphenyl		96.8 %	65	135	"	н	"	**	
Metals by EPA 6010B									
Antimony	ND	3.0	mg/kg	1	7112808	11/28/07	12/05/07	EPA 6010B	
Silver	ND	2.0	11	н	łŧ	н	ч	tf .	
Arsenic	ND	5.0	11	н	#	п	и	H	
Barium	150	1.0	13	Ħ	15	11	4ξ	н	
Beryllium	ND	1.0	117	n	**	11	н	н	
Cadmium	ND	2.0	н	0	n	10	11-	α	
Chromium	29	2.0	1)	n	**	0	D	ff.	
Cobalt	13	2.0	14	н	0	n	M	1 1	
Copper	18	1.0	17	n	Ħ	н	н	н	
Lead	3.2	3.0	14	n	#	11	и	B	
Molybdenum	ND	1.0	u	н	11	И	н	45	
Nickel	15	2.0	fl	f#	"	"	#	п	
Selenium	ND	5.0	11	н	ti .	н	н	Ħ	
Thallium	ND	2.0	u	11	31	11	n	n	
Vanadium	73	5.0	11	11	п	н	н	"	
Zinc	49	1.0	19	н	11	11	11	1+	
Cold Vapor Extraction EPA 7470/7471									
Mercury	ND	0.10	mg/kg	1	7112809	11/28/07	11/30/07	EPA 7471A Soil	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]
Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B2-5 T701523-07 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Volatile Organic Compounds by I	EPA Method 826	0B							
Bromobenzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Bromochloromethane	ND	5.0	16	91	16	11	17	11	
Bromodichloromethane	ND	5.0	H	H	11	11	11	н	
Bromoform	ND	5.0	17	н	n	u	**	н	
Bromomethane	ND	5.0	и	ri	1)	tr	η	н	
n-Butylbenzene	ND	5.0	11	*1	ti	н	*	n	
sec-Butylbenzene	ND	5.0	ŧŧ	n	D.	11	и	b	
tert-Butylbenzene	ND	5.0	н	11	н	н	н	I†	
Carbon tetrachloride	ND	5.0	**	н	11	**	н -	Ħ	
Chlorobenzene	ND	5.0	ti	11	n	n	H	19	
Chloroethane	ND	5.0	Ħ	ti ti	πŧ	**	#f	11	
Chloroform	ND	5.0	14	n	n	n	n	H	
Chloromethane	ND	5.0	i f	n	n	75	it.	Ħ	
2-Chlorotoluene	ND	5.0	19	11	u	п	h	17	
4-Chlorotoluene	ND	5.0	14	ч	tt	11	11	11	
Dibromochloromethane	ND	5.0	ti	ц	n	18	ы	4	
1,2-Dibromo-3-chloropropane	ND	5.0	18	e	79	11	19	n	
1,2-Dibromoethane (EDB)	ND	5.0	н	н	0	0	**	я	
Dibromomethane	ND	5.0	19	11	11	11	11	и	
1.2-Dichlorobenzene	ND	5.0	19	н	11	15	ŧı	а	
1,3-Dichlorobenzene	ND	5.0	21	Ħ	**	n	11	n	
1,4-Dichlorobenzene	ND	5.0	t+	n	41	ti.	tı	н	
Dichlorodifluoromethane	ND	5.0	H	rt		н	n	н	
1,1-Dichloroethane	ND	5.0	19	н	11	и	11	ts	
1,2-Dichloroethane	ND	5.0	19	44	н	н :	п	14	
1,1-Dichloroethene	ND	5.0	19	71	n	t†	n	н	
cis-1,2-Dichloroethene	ND	5.0	11	11	n	н	н	D	
trans-1,2-Dichloroethene	ND	5.0	н	u	N	и	n	at	
1,2-Dichloropropane	ND	5.0	19	11	и	н	n	IF	
1,3-Dichloropropane	ND	5.0		AT	**	11	ħ	Ħ	
2,2-Dichloropropane	ND	5.0	17	**	*1	н	н	11	
	ND ND	5.0	19	n	11	11	15	41	
1,1-Dichloropropene	ND ND	5.0	18	**	п	11	ţ\$	11	
cis-1,3-Dichloropropene		5.0	13	н	ar .	11	19	st	
trans-1,3-Dichloropropene	ND ND	5.0	11	11	, H	m m		,,	
Hexachlorobutadiene		5.0	31		31	"	"	н	
Isopropylbenzene	ND		н	11:	и	н	н	it i	
p-Isopropyltoluene	ND	5.0	11	н		**	н ,,	9	
Methylene chloride	ND	5.0		11	n h	и	n	31	
Naphthalene	ND	5.0	n 		11	11	11		
n-Propylbenzene	ND	5.0	11	n	**	"	15	31	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tayons

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Reported: 12/10/07 17:03 Project Manager: Brian Brennan

B2-5 T701523-07 (Soil)

Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
SunStar La	borator	ies, Inc.					
60B							
5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
5.0	11	n	11	tr	n	P	
5.0	11	41	М	n	п	ti	
5.0	31	**	**	**	н	łł	
5.0	19	11	н	n	10	н	
5.0	F1	n	6	н	Ħ	15	
5.0	n	11	н	н	ŢE.	š1	
5.0	н	н	17	ti .	н	17	
5.0	71	t)	n	n	15	17	
5.0	и	Ħ	15	11	n	It	
5.0	#	н	Ħ	11	11	н	
5.0	н	n	47	ii.	н	н	
5.0	71	и	н	11	11	n	
5.0	15	н	16	0	**	н	
5.0	n	н	н	71	11	н	
5.0	u	11	11	н	rs	#1	
5.0	11	"	н	11	11	. н	
5.0	и	0	n	1)	м	11	
5.0	11	**	м	n	ff.	н	
20	11	11	**	k)	n	18	
500	13	н	**	11	м	Ħ	
90.2 %	81-	118	"	"	n	"	
113 %	73-	127	"	#	"	"	
104 %	85-	115	"	"	"	"	
	SunStar La 50B 5.0 5.0 5.0 5.0 5.0 5.0 5.0 5.0 5.0 5.	Limit Units SunStar Laborator 50B 5.0 ug/kg 5.0 "	Limit Units Dilution	Limit Units Dilution Batch	Limit Units Dilution Batch Prepared	Limit Units Dilution Batch Prepared Analyzed	Limit Units Dilution Batch Prepared Analyzed Method

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tayons

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B3-5 T701523-11 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		SunStar L							
Metals by EPA 6010B									
Lead	6.4	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by EP	A Method 8260B	3							
Benzene	ND	5.0	ug/kg	1.	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	19	*	4	n	(1	I †	
Ethylbenzene	ND	5.0	11	n	н	11	и	¥r	
m,p-Xylene	ND	5.0	Ħ	н	η	н	e	1t	
o-Xylene	ND	5.0	11	н	M	11	н	11	
Methyl tert-butyl ether	ND	20	51	м	,,	п	11	11	
C6-C12 (GRO)	ND	500	19	0	н	17	н	н	
Surrogate: 4-Bromofluorobenzene		89.2 %	81-1	18	"	ir	33	"	
Surrogate: Dibromofluoromethane		116 %	73-1	27	"	u	"	#	
Surrogate: Toluene-d8		103 %	<i>85-1</i>	15	"	"	"	и	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Albert Vargas, Project Coordinator

allee Trangas

Page 8 of 30

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B3-10 T701523-12 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
	S	unStar L	aboratori	es, Inc.					
Metals by EPA 6010B									
Lead	4.0	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by E	PA Method 8260B								
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	17	*1	•	41	17	51	
Ethylbenzene	ND	5.0	ŧŧ	п	н	н	FI.	н	
m,p-Xylene	ND	5.0	11	11	n	H	м	19	
o-Xylene	ND	5.0	19	17	**	11	"	и	
Methyl tert-butyl ether	ND	20	H	17	Ħ	"	H	18	
C6-C12 (GRO)	ND	500	n	11	19	11	11	11	
Surrogate: 4-Bromofluorobenzene		89.1 %	81-1	18	"	u	"	u	
Surrogate: Dibromofluoromethane		115 %	73-1	27	"	"	"	"	
Surrogate: Toluene-d8		103 %	85-1	15	"	11	#	"	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document, This analytical report must be reproduced in its entirety.

allee Tragas

Project: Al's Corner

4730 Palm Avenue, Suite 213

Project Number: [none]

Reported:

La Mesa CA, 91941

Project Manager: Brian Brennan

12/10/07 17:03

B3-15 T701523-13 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		unStar L							
Metals by EPA 6010B									
Lead	5.0	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by E	PA Method 8260B								
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	n	н	11	М	II.	Ħ	
Ethylbenzene	ND	5.0	19	tt	н	ŧŧ	4	31	
m,p-Xylene	ND	5.0	Iŧ	6	řŧ	tt	н	н	
o-Xylene	ND	5.0	н	n	**	11	15	n	
Methyl tert-butyl ether	ND	20	11	**	41	н	n	11-	
C6-C12 (GRO)	ND	500	н	n	47	10	17	11	
Surrogate: 4-Bromofluorobenzene		88.6 %	81-1	18	11	ıı .	a	и	
Surrogate: Dibromofluoromethane		120 %	73-1	27	"	"	и	n	
Surrogate: Toluene-d8		104 %	85-1	15	"	**	11	"	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Targas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B4-5 T701523-17 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar L	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead	3.6	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by El	PA Method 8260	В							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	11	**	10	6	n	ž†	
Ethylbenzene	ND	5.0	n	н	н	tf	41	ti	
m,p-Xylene	ND	5.0	11	*1	0	11	18	11	
o-Xylene	ND	5.0	19	9	B	11	ĸ	11	
Methyl tert-butyl ether	ND	20	n	11	и	h	м	н	
C6-C12 (GRO)	ND	500	19	н	н	51	Ħ	9	
Surrogate: 4-Bromofluorobenzene		88.2 %	81-	118	"	и	и	11	
Surrogate: Dibromofluoromethane		116 %	73-	127	и	"	"	"	
Surrogate: Toluene-d8		104 %	85-	115	н	"	"	rr .	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tayas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B4-10 T701523-18 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead	4.8	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by EPA	A Method 8260I	3							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	11	"	0	"	н	H	
Ethylbenzene	ND	5.0	11	o o	10	п	it	"	
m,p-Xylene	ND	5.0	11	11	13	10	н	11	
o-Xylene	ND	5.0	Ħ	11	n	**	11	н	
Methyl tert-butyl ether	ND	20	11	Ħ	Ħ	н	rt	44	
C6-C12 (GRO)	ND	500	11	н	tf		н	lt	
Surrogate: 4-Bromofluorobenzene		90.0 %	81	118	n	n	n	"	
Surrogate: Dibromofluoromethane		121 %	73-	127	**	"	51	n	
Surrogate: Toluene-d8		106 %	85-	115	11	"	"	"	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Albert Vargas, Project Coordinator

allee Wargas

Page 12 of 30

4730 Palm Avenue, Suite 213 La Mesa CA, 91941 Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B4-15 T701523-19 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
R		SunStar La	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead	4.4	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by EPA	A Method 8260)B							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	II	11	11	н	11	н	
Ethylbenzene	ND	5.0	33	19	н	**	15	11	
m,p-Xylene	ND	5.0	11	91	31	п	ď	H	
o-Xylene	ND	5.0	19	n	Ħ	11	H	n	
Methyl tert-butyl ether	ND	20	39	н	H	n	н	11	
C6-C12 (GRO)	ND	500	ır	11	11	11	11	11	·
Surrogate: 4-Bromofluorobenzene		88.8 %	81-	118	11	n	"	"	
Surrogate: Dibromofluoromethane		114 %	73-	127	11	11	n	n .	
Surrogate: Toluene-d8		104 %	85-	115	"	tt	"	"	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tayons

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]
Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B5-5 T701523-23 (Soil)

Analyte 1	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Note
		SunStar La	aborator	ies, Inc.					
Extractable Petroleum Hydrocarbons by 80)15B								
C6-C12 (GRO)	ND	0.10	mg/kg	1	7112714	11/27/07	11/27/07	EPA 8015B	
C13-C28 (DRO)	ND	0.10	11	16	tt.	ti	49	"	
C29-C40 (MORO)	ND	0.10	н	11	6	н	н	н	
Surrogate: p-Terphenyl		78.4 %	65	135	н	n	#	"	
Metals by EPA 6010B									
Antimony	ND	3.0	mg/kg	1	7112808	11/28/07	12/05/07	EPA 6010B	
Silver	ND	2.0	?1	и	н	ч	н	n	
Arsenic	ND	5.0	11	75	11	17	44	et	
Barium	93	1.0	11	¥£	TH	н	п	1t	
Beryllium	ND	1.0	19	11	şı.	н	12/05/07	51	
Cadmium	ND	2.0	16	ŧŧ	н	11	12/05/07	н	
Chromium	64	2.0	n	н	n	n	н	lt.	
Cobalt	22	2.0	11	0	0	a.	16	21	
Copper	40	1.0	19	11	ы	н	41	н	
Lead	6.8	3.0	11	н	Ħ	н	н	iř	
Molybdenum	ND	1.0	11	tt	11	н	11	u	
Nickel	32	2.0	"	ıı	**	n	tt	n	
Selenium	ND	5.0	11	17	Ħ	n	н	34	
Thallium	ND	2.0	11	н	М	19	н	If	
Vanadium	95	5.0	O	п	11	n	n	11	
Zine	62	1.0	н	15	ŧī	q	11	И	
Cold Vapor Extraction EPA 7470/7471									
Mercury	ND	0.10	mg/kg	1	7112809	11/28/07	11/30/07	EPA 7471A Soil	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Targas

4730 Palm Avenue, Suite 213

Project: Al's Corner

Project Number: [none]

Reported: 12/10/07 17:03

La Mesa CA, 91941

Project Manager: Brian Brennan

B5-5 T701523-23 (Soil)

Result	Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Note
		aborator	ies, Inc.					
Aethod 826			, ·					
ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	···········
ND	5.0	11	n	"	н	u	11	
ND	5.0	11	ήt	н	h	н	н	
ND	5.0	17	łr	u	**	19	μ	
ND	5.0	11	h	Ħ	11	м	и	
ND	5.0	н	41	ft	0	11	H	
ND	5.0	11	н	17	н	11	11	
ND	5.0	1)	н	н	н	н	Ħ	
ND	5.0	19	н	n	11	н	n ·	
ND	5.0	11	44	11	9	rt	It.	
ND	5.0	14	п	tt	н	**	**	
ND	5.0	11	n	н	ti	н	ы	
ND	5.0	ŧr	11	11	a	н	u	
ND	5.0	It	n	н	**	н	"	
ND	5.0	11	"	11	tt.	**	H	
ND	5.0	1)	н	0	n	1f	11	
	5.0	19	n	н	н	п	ឡ	
	5.0	tr	н	п	11	п	н	
		17	n	11	0	11	n	
		91	и	o o	н	11	Ħ	
		n	n	н	n	н	Ħ	
		11	af	†I	n	н	H	
		31	ti	п	tt	Ħ	м	
		11	11	v	11	11	H	
		15		11	11-	15	11	
	-	11	11	h	н	и	н	
		n	11	11	tt	н	D	
		71	**	11	11	11	1f	
		19	к	11	rt	4	11	
		11	11	н	н	н	п	
		e	44	tt.	n	**	11	
		59	34	11	ท	19	n	
		н	я	0	8	11	0	
		n	н	re	n	11	Ħ	
		17	П	м	и	н	TF.	
		t)		11	0	11	11	
		15	н	м	"	п	51	
		п	B	н	н	n	IE	
		19	11	17	11	В	Ħ	
		17	н	ŧr	н	11	N	
	ND N	ND 5.0 ND	ND S.0 ug/kg ND S.0 ug/kg ND S.0 " ND S.0 "	ND 5.0 ug/kg 1 ND 5.0 " ND 5.0	Method 8260B ND 5.0 ug/kg 1 7112717 ND 5.0 " " " ND 5.0 " " "	ND 5.0 ug/kg 1 7112717 11/27/07 ND 5.0 " " " " " " ND 5.0 " " " " " " " ND 5.0 " " " " " " " ND 5.0 " " " " " " " ND 5.0 " " " " " " " " ND 5.0 " " " " " " " " ND 5.0 " " " " " " " " ND 5.0 " " " " " " " " " ND 5.0 " " " " " " " " " ND 5.0 " " " " " " " " " " ND 5.0 " " " " " " " " " " ND 5.0 " " " " " " " " " " " ND 5.0 " " " " " " " " " " " ND 5.0 " " " " " " " " " " " " " " ND 5.0 " " " " " " " " " " " " " " " " " " "	ND 5.0 ug/kg 1 7112717 11/27/07 11/29/07 ND 5.0 " " " " " " " " " " " " " " " " " " "	ND 5.0 ug/kg 1 7112717 11/27/07 11/29/07 EPA 8260B ND 5.0 " " " " " " " " " " " " " " " " " " "

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]
Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B5-5 T701523-23 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
	S	unStar L	aborator	ies, Inc.					
Volatile Organic Compounds by EPA	Method 8260B								
Styrene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
1,1,2,2-Tetrachloroethane	ND	5.0	п	н	n	1)	11	н	
1,1,1,2-Tetrachloroethane	ND	5.0	и	rt	н	11	11	n	
Tetrachloroethene	ND	5.0	11	**	н	O.	1)	н	
1,2,3-Trichlorobenzene	ND	5.0	11	н	tt	N	n	Ħ	
1,2,4-Trichlorobenzene	ND	5.0	19	H	41	n	н	10	
1,1,2-Trichloroethane	ND	5.0	Ħ	13	p	19	H	U-	
1,1,1-Trichloroethane	ND	5.0	17	41	q	н	н	49	
Trichloroethene	ND	5.0	Ħ	11	41	в	"	Hs.	
Trichlorofluoromethane	ND	5.0	11	**	п	11	11	н	
1,2,3-Trichloropropane	ND	5.0	19	н	n	40	11	31	
1,3,5-Trimethylbenzene	ND	5.0	19	11	H	11	44	Ħ	
1,2,4-Trimethylbenzene	ND	5.0	11	н	н	11	ft	"	
Vinyl chloride	ND	5.0	11	**	11	н	н	18	
Benzene	ND	5.0	11	11	11	91	н	н	
Toluene	ND	5.0	11	·π	#	н	н	11	
Ethylbenzene	ND	5.0	11	11	11	н	н	D.	
m,p-Xylene	ND	5.0	17	11	11	11	41	н	
o-Xylene	ND	5.0	51	h	н	11	τř	21	
Methyl tert-butyl ether	ND	20	Ħ	Ħ	Ħ	15	41	Ħ	
C6-C12 (GRO)	ND	500	11	h	н	†¢	**	н	
Surrogate: 4-Bromofluorobenzene		86.5 %	81	-118	I#	"	(1	"	
Surrogate: Dibromofluoromethane		116 %	73-	-127	"	"	n	"	
Surrogate: Toluene-d8		104 %	85	-115	и	и	11	"	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B6-5 T701523-26 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar L	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead .	4.0	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by l	EPA Method 8260	3							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	15	11	н	ti	17	19	
Ethylbenzene	ND	5.0	Ħ	н	11-	11	14	н	
m,p-Xylene	ND	5.0	11	H	Ħ	49	11	Ħ	
o-Xylene	ND	5.0	11	н	17	n	н	я	
Methyl tert-butyl ether	ND	20	*)	н	ч	11	н	μ	
C6-C12 (GRO)	ND	500	!!	н	1)		н	11	
Surrogate: 4-Bromofluorobenzene		86.5 %	81-	118	u	u	11	**	
Surrogate: Dibromofluoromethane		113 %	73-	127	"	μ	"	п	
Surrogate: Toluene-d8		103 %	85-	115	"	"	"	N .	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Albert Vargas, Project Coordinator

aller Tagas

Page 17 of 30

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B6-10 T701523-27 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar L	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead	11	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by EF	A Method 8260	В							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	19	. 4	n	ŧI	n	11	
Ethylbenzene	ND	5.0	п	11	n	tt	11	It	
m,p-Xylene	ND	5.0	19	n	н	•	n	11	
o-Xylene	ND	5.0	н	•	10	n	11	D	
Methyl tert-butyl ether	ND	20	11	H	**	u	н	17	
C6-C12 (GRO)	ND	500	11	. 11	15	n	11	IF.	
Surrogate: 4-Bromofluorobenzene		86.8 %	81-	118	tr .	11	"	и	
Surrogate: Dibromofluoromethane		119 %	73-	127	"	n	"	"	
Surrogate: Toluene-d8		103 %	85-	115	"	#	"	"	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tayas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B6-15 T701523-28 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar L	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead	ND	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by EPA	A Method 8260	В							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	13	11	R	11	n	Ħ	
Ethylbenzene	ND	5.0	11	it	н	ĸ	н	n,	
m,p-Xylene	ND	5.0	н	**	e	н	15	н	
o-Xylene	ND	5.0	n	n	et	"	н	в	
Methyl tert-butyl ether	ND	20	13	н	17	u	11	н	
C6-C12 (GRO)	ND	500	н	et.	н .	19	11	11	
Surrogate: 4-Bromofluorobenzene		87.2 %	81-	118	"	n	#	и	
Surrogate: Dibromofluoromethane		121 %	73-	127	"	"	"	"	
Surrogate: Toluene-d8		103 %	85-	115	11	и	"	"	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tayon

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B7-5 T701523-30 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead	ND	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by EPA	A Method 8260	В							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	1)	п	н	n	ч	TF.	
Ethylbenzene	ND	5.0	1)	u	п	m	9	11	
m,p-Xylene	ND	5.0	ŦĖ	11	18	15	11	11	
o-Xylene	ND	5.0	11	4	41	11	н	и	
Methyl tert-butyl ether	ND	20	11	н	н	11	п	n	
C6-C12 (GRO)	ND	500	rŧ	н	н	er	u	Tf	
Surrogate: 4-Bromofluorobenzene		91.9 %	81-	118	**	17	n	H	
Surrogate: Dibromofluoromethane		116 %	73-	127	17	"	"	o	
Surrogate: Toluene-d8		104 %	85-	115	"	"	н	n	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

Albert Vargas, Project Coordinator

aller Tangas

Page 20 of 30

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B7-10 T701523-31 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aborator	ies, Inc.					
Metals by EPA 6010B									
Lead	8.4	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by EPA M	lethod 826	0B							
Benzene	ND	5.0	ug/kg	1	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	Ħ	11	н	н	н	11	
Ethylbenzene	ND	5.0	†1	n	н	н	H	11	
m,p-Xylene	ND	5.0	н	ŧ	n	н	н	H	
o-Xylene	ND	5.0	"	*1	n	н	n	11	
Methyl tert-butyl ether	ND	20	1+	н ,	н	4	n	Ħ	
C6-C12 (GRO)	ND	500	B	н	н	н	li li	11	
Surrogate: 4-Bromofluorobenzene		88.1 %	81-	118	п	"	"	n	
Surrogate: Dibromofluoromethane		116 %	<i>73-</i>	127	44	"	"	"	
Surrogate: Toluene-d8		109 %	85-	115	"	n	"	H	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Vargas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

B7-15 T701523-32 (Soil)

Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
		SunStar La	aboratori	es, Inc.					
Metals by EPA 6010B				_					
Lead	4.8	3.0	mg/kg	1	7113005	11/30/07	12/06/07	EPA 6010B	
Volatile Organic Compounds by EP	A Method 8260	В							
Benzene	ND	5.0	ug/kg	1.	7112717	11/27/07	11/29/07	EPA 8260B	
Toluene	ND	5.0	n	н	1)	13	\$1	23	
Ethylbenzene	ND	5.0	н	н	н	н	tt	ч	
m,p-Xylene	ND	5.0	11	n	43	Ħ	n	Ħ	
o-Xylene	ND	5.0	19	"	н	tf	11	19	
Methyl tert-butyl ether	ND	20	11	ŧſ	Tŧ	н	18	0	
C6-C12 (GRO)	ND	500	0	11	н	11	H	n	
Surrogate: 4-Bromofluorobenzene		86.4 %	81-1	18	п	и	u	"	
Surrogate: Dibromofluoromethane	•	116 %	73-1	27	17	"	"	"	
Surrogate: Toluene-d8		106 %	85-1	15	rr	"	"	n	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

4730 Palm Avenue, Suite 213

Project: Al's Corner

Project Number: [none]

Reporting

Reported: 12/10/07 17:03

RPD

%REC

La Mesa CA, 91941

Project Manager: Brian Brennan

Extractable Petroleum Hydrocarbons by 8015B - Quality Control SunStar Laboratories, Inc.

Spike

Source

Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch 7112714 - EPA 3550B GC										
Blank (7112714-BLK1)				Prepared	& Analyz	ed: 11/27/	07			
Surrogate: p-Terphenyl C13-C28 (DRO)	92.4 ND	0.10	mg/kg	100	de Al-A-A-A-A-A-A-A-A-A-A-A-A-A-A-A-A-A-A-	92.4	65-135			
LCS (7112714-BS1)				Prepared	& Analyz	ed: 11/27/	07			
Surrogate: p-Terphenyl	94.7		mg/kg	100		94.7	65-135	~		
C13-C28 (DRO)	470	0.10	11	500		93.7	75-125			
Matrix Spike (7112714-MS1)	So	urce: T70152	21-01	Prepared	: 11/27/07	Analyzeo	1: 11/28/07			
Surrogate: p-Terphenyl	106		mg/kg	100	7,1111//	106	65-135			
C13-C28 (DRO)	490	0.10	н	500	ND	97.5	75-125			
Matrix Spike Dup (7112714-MSD1)	Se	ource: T7015	21-01	Prepared	: 11/27/07	Analyzed	1: 11/28/07			
Surrogate: p-Terphenyl	108	-/	mg/kg	100		108	65-135			
C13-C28 (DRO)	580	0.10	н	500	ND	116	75-125	16.9	20	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

alber Vargas

4730 Palm Avenue, Suite 213

Project: Al's Corner

Project Number: [none]

Reported: 12/10/07 17:03

La Mesa CA, 91941

Project Manager: Brian Brennan

Metals by EPA 6010B - Quality Control SunStar Laboratories, Inc.

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 7112808 - EPA 3051										
Blank (7112808-BLK1)				Prepared:	11/28/07	Analyzed	: 12/03/07			
Antimony	ND	3.0	mg/kg							
Silver	ND	2.0	21							
Arsenic	ND	5.0	u							
Barium	ND	1.0	tt							
Beryllium	ND	1.0	n							
Cadmium	ND	2.0	ee							
Chromium	ND	2.0	n							
Cobalt	ND	2.0	21							
Copper	ND	1.0	u							
Lead	ND	3.0	11							
Molybdenum	ND	1.0	21							
Nickel	ND	2.0	В							
Selenium	ND	5.0	n							
Thallium	ND	2.0	n							
Vanadium	ND	5.0	te							
Zinc	ND	1.0	В							
LCS (7112808-BS1)				Prepared:	: 11/28/07	Analyzeo	1: 12/03/07			
Arsenic	118	5.0	mg/kg	100		118	75-125			
Barium	113	1.0	n	100		113	75-125			
Cadmium	112	2.0	41	100		112	75-125			
Chromium	112	2.0	Ħ	100		112	75-125			
Lead	111	3.0	II	100		111	75-125			
Matrix Spike (7112808-MS1)	Se	ource: T70152	20-01	Prepared	: 11/28/07	Analyze	d: 12/03/07	!		QM-0
Arsenic	90.4	5.0	mg/kg	100	ND	90.4	75-125			
Barium	278	1.0	н	100	233	45.6	75-125			QM-0
Cadmium	86.3	2.0	IS	100	4.80	81.5	75-125			
Chromium	185	2.0	it	100	282	NR	75-125			QM-0
Lead	775	3.0	и	100	954	NR	75-125			QM-0

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Targas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none] Project Manager: Brian Brennan Reported:

RPD

%REC

12/10/07 17:03

Metals by EPA 6010B - Quality Control

SunStar Laboratories, Inc.

Spike

Source

Reporting

Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch 7112808 - EPA 3051										
Matrix Spike Dup (7112808-MSD1)	Sour	ce: T70152	20-01	Prepared:	11/28/07	Analyzed	1: 12/03/07			QM-07
Arsenic	105	5.0	mg/kg	100	ND	105	75-125	15.1	20	
Barium	354	1.0	n	100	233	121	75-125	23.9	20	QM-07
Cadmium	97.3	2.0	tt	100	4.80	92.5	75-125	12.0	20	
Chromium	179	2.0	Ħ	100	282	NR	75-125	3.32	20	QM-07
Lead	1020	3.0	H	100	954	60.8	75-125	26.8	20	QM-07
Batch 7113005 - EPA 3051										
Blank (7113005-BLK1)				Prepared:	11/30/07	Analyzed	l: 12/06/07			
Lead	ND	3.0	mg/kg	O.A.C.						
LCS (7113005-BS1)				Prepared:	11/30/07	Analyzed	I: 12/06/07			
Lead	98.6	3.0	mg/kg	100		98.6	75-125		11-	
Matrix Spike (7113005-MS1)	Sour	ce: T70152	23-01	Prepared	11/30/07	Analyzed	1: 12/06/07			
Lead	109	3.0	mg/kg	100	5.60	103	75-125			
Matrix Spike Dup (7113005-MSD1)	Sour	rce: T70152	23-01	Prepared	: 11/30/07	Analyzeo	1: 12/06/07			
Lead	106	3.0	mg/kg	100	5.60	100	75-125	2.61	20	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tangas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

Cold Vapor Extraction EPA 7470/7471 - Quality Control SunStar Laboratories, Inc.

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch 7112809 - EPA 7471A Soil										
Blank (7112809-BLK1)				Prepared:	11/28/07	Analyzed	l: 11/30/07			
Mercury	ND	0.10	mg/kg							
LCS (7112809-BS1)				Prepared:	11/28/07	Analyzed	: 11/30/07			
Mercury	0.446	0.10	mg/kg	0.417		107	80-120			
Matrix Spike (7112809-MS1)	Sou	rce: T70153	32-16	Prepared:	11/28/07	Analyzec	l: 11/30/07			
Mercury	0.392	0.10	mg/kg	0.417	ND	94.1	75-125			
Matrix Spike Dup (7112809-MSD1)	Sou	rce: T70153	32-16	Prepared:	11/28/07	Analyzec	l: 11/30/07			
Mercury	0.448	0.10	mg/kg	0.417	ND	108	75-125	13.3	20	

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tagas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

Volatile Organic Compounds by EPA Method 8260B - Quality Control SunStar Laboratories, Inc.

			·····							į.
		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes

Batch	7112717	- EPA	5030	GCMS
-------	---------	-------	------	-------------

Blank (7112717-BLK1)				Prepared: 11/2	27/07 Analyzed	: 11/29/07	
Surrogate: 4-Bromofluorobenzene	7.26		ug/kg	8.00	90.8	81-118	
Surrogate: Dibromofluoromethane	8.68		H	8.00	108	73-127	
Surrogate: Toluene-d8	8.25		31	8.00	103	85-115	
Bromobenzene	ND	5.0	41				
Bromochloromethane	ND	5.0	п				
Bromodichloromethane	ND	5.0	н				
Bromoform	ND	5.0	ĮI.				
Bromomethane	ND	5.0	15				
n-Butylbenzene	ND	5.0	Ħ				
sec-Butylbenzene	ND	5.0	11				
tert-Butylbenzene	ND	5.0	IŢ				
Carbon tetrachloride	ND	5.0	и				
Chlorobenzene	ND	5.0	41				
Chloroethane	ND	5.0	11				
Chloroform	ND	5.0	n				
Chloromethane	ND	5.0	11				
2-Chlorotoluene	ND	5.0	11				
4-Chlorotoluene	ND	5.0	#				
Dibromochloromethane	ND	5.0	įt.				
1,2-Dibromo-3-chloropropane	ND	5.0	Ħ				
1,2-Dibromoethane (EDB)	ND	5.0	В				
Dibromomethane	ND	5.0	ti				
1,2-Dichlorobenzene	ND	5.0	H				
1,3-Dichlorobenzene	ND	5.0	9				
1,4-Dichlorobenzene	ND	5.0	н				
Dichlorodifluoromethane	ND	5.0	Ħ				
1,1-Dichloroethane	ND	5.0	II.				
1,2-Dichloroethane	ND	5.0	#				
1,1-Dichloroethene	ND	5.0	В				
cis-1,2-Dichloroethene	ND	5.0	17				
trans-1,2-Dichloroethene	ND	5.0	tt				
1,2-Dichloropropane	ND	5.0	н				
1,3-Dichloropropane	ND	5.0	II				
2,2-Dichloropropane	ND	5.0					
1,1-Dichloropropene	ND	5.0	Ħ				
cis-1,3-Dichloropropene	ND	5.0	31				
trans-1,3-Dichloropropene	ND	5.0	II.				
Hexachlorobutadiene	ND	5.0	н				
Isopropylbenzene	ND	5.0	11				
p-Isopropyltoluene	ND	5.0	ıt				
Methylene chloride	ND	5.0	It				
Methylene chloride	ND	5.0	16				

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Tangas

4730 Palm Avenue, Suite 213

Project: Al's Corner

Project Number: [none]

Reporting

Reported: 12/10/07 17:03

RPD

%REC

La Mesa CA, 91941

Project Manager: Brian Brennan

Volatile Organic Compounds by EPA Method 8260B - Quality Control SunStar Laboratories, Inc.

Spike

Source

A color	Dogulf	Reporting Limit	Units	Spike Level	Result	%REC	Limits	RPD	Limit	Notes
Analyte	Result	Linit	Omis	revei	Result	70.N.L.C	Diffica	101 10	1711111	110000
Batch 7112717 - EPA 5030 GCMS						···				
Blank (7112717-BLK1)				Prepared:	11/27/07	Analyzed	: 11/29/07		had of the same of	
Naphthalene	ND	5.0	ug/kg							
n-Propylbenzene	ND	5.0	11							
Styrene	ND	5.0	Ħ							
1,1,2,2-Tetrachloroethane	ND	5.0	II.							
1,1,1,2-Tetrachloroethane	ND	5.0	Ħ							
Tetrachloroethene	ND	5.0	п							
1,2,3-Trichlorobenzene	ND	5.0	12							
1,2,4-Trichlorobenzene	ND	5.0	н							
1,1,2-Trichloroethane	ND	5.0	Ħ							
1,1,1-Trichloroethane	ND	5.0	-11							
Trichloroethene	ND	5.0	R							
Trichlorofluoromethane	ND	5.0	ŧ							
1,2,3-Trichloropropane	ND	5.0	n							
1,3,5-Trimethylbenzene	ND	5.0	17							
1,2,4-Trimethylbenzene	ND	5.0	83							
Vinyl chloride	ND	5.0	31							
Benzene	ND	5.0	It							
Toluene	ND	5.0	11							
Ethylbenzene	ND	5.0	18							
m,p-Xylene	ND	5.0	H.							
o-Xylene	ND	5.0	ti							
Methyl tert-butyl ether	ND	20	Ħ							
C6-C12 (GRO)	ND	500	н							
LCS (7112717-BS1)				Prepared	: 11/27/07	7 Analyze	d: 12/01/0	7		
Surrogate: 4-Bromofluorobenzene	8.11		ug/kg	8.00		101	81-118			
Surrogate: Dibromofluoromethane	7.98		"	8.00		99.8	73-127			
Surrogate: Toluene-d8	7.96		16	8.00		99.5	85-115			
Chlorobenzene	91.7	5.0	11	100		91.7	75-125			
1.1-Dichloroethene	97.2	5.0	34	100		97.2	75-125			
Trichloroethene	97.4	5.0	It	100		97.4	75-125			
Benzene	93.0	5.0	н	100		93.0	75-125			
Toluene	91.9	5.0	tt	100		91.9	75-125			

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allee Tayas

4730 Palm Avenue, Suite 213

La Mesa CA, 91941

Project: Al's Corner

Project Number: [none]

Reporting

Project Manager: Brian Brennan

Reported: 12/10/07 17:03

RPD

%REC

Volatile Organic Compounds by EPA Method 8260B - Quality Control SunStar Laboratories, Inc.

Spike

Source

Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch 7112717 - EPA 5030 GCMS										
Matrix Spike (7112717-MS1)	Sour	ce: T70152	3-03	Prepared:	11/27/07	Analyzed	l: 12/01/07			
Surrogate: 4-Bromofluorobenzene	7.87		ug/kg	8.00		98.4	81-118			
Surrogate: Dibromofluoromethane	7.89		17	8.00		98.6	73-127			
Surrogate: Toluene-d8	8.03		11	8.00		100	85-115			
Chlorobenzene	61.2	5.0	31	100	ND	61.2	75-125			QM-0
1,1-Dichloroethene	78.4	5.0	lF.	100	ND	78.4	75-125			
Trichloroethene	70.0	5.0	41	100	ND	70.0	75-125			QM-0'
Benzene	74.3	5.0	li	100	ND	74.3	75-125			QM-01
Toluene	63.6	5.0	II	100	ND	63.6	75-125			QM-0
Matrix Spike Dup (7112717-MSD1)	Som	rce: T70152	23-03	Prepared:	11/27/07	Analyzeo	i: 12/01/07			
Surrogate: 4-Bromofluorobenzene	7.94		ug/kg	8.00		99.2	81-118	770		
Surrogate: Dibromofluoromethane	7.42		"	8.00		92.8	73-127			
Surrogate: Toluene-d8	7.92		rt	8.00		99.0	85-115			
Chlorobenzene	60.8	5.0	ы	100	ND	60.8	75-125	0.737	20	QM-0
1,1-Dichloroethene	50.5	5.0	1I	100	ND	50.5	75-125	43.2	20	QM-07 QR-0
Trichloroethene	58.4	5.0	n	100	ND	58.4	75-125	17.9	20	QM-0
Benzene	63.3	5.0	n	100	ND	63.3	75-125	16.0	20	QM-0
Toluene	56.2	5.0	ır	100	ND	56.2	75-125	12.3	20	QM-0

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

allen Targas

Project: Al's Corner

4730 Palm Avenue, Suite 213

Project Number: [none]

Reported: 12/10/07 17:03

La Mesa CA, 91941

Project Manager: Brian Brennan

Notes and Definitions

QR-02 The RPD result exceeded the QC control limits; however, both percent recoveries were acceptable. Sample results for the QC

batch were accepted based on percent recoveries and completeness of QC data.

QM-07 The spike recovery and or RPD was outside acceptance limits for the MS and/or MSD. The batch was accepted based on

acceptable LCS recovery.

DET Analyte DETECTED

ND Analyte NOT DETECTED at or above the reporting limit

NR Not Reported

dry Sample results reported on a dry weight basis

RPD Relative Percent Difference

SunStar Laboratories, Inc.

The results in this report apply to the samples analyzed in accordance with the chain of custody document. This analytical report must be reproduced in its entirety.

aller Vargas

SunStar Laboratories, Inc. 3002 Dow Ave., Ste. 212 Tustin, CA 92780 714-505-4010

Relinquished by: (signature) Relinquished by: (signature) Sample dioposal instructions: Dis	Address: 7750 / Manager: 6175- 6165- 6175- 6185- 6175- 6185-	Client: EEL
/Time	1246 Dath / Tide / 1246	
	Sample Container Type Sample Live Romanner	# 1 - 0
Date / Time Date / Time	8260 8260 + OXY 8260 + OXY 8260 BTEX, OXY only 8270 8021 BTEX Solution 8015M (gasoline) 172 173 174 175	Date:
Chain of Custod Seals Received good	8015M Ext./Carbon Chain 6010/7000 Title 22 Metals XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	1
7.8 Coren	Client Pro	Page:/
Cosunty	Comments/Preservative Total # of containers	or .3
P. CONT.	1016-899-619 nsing	පිටු

Chain of Custody Record

SunStar Laboratories, Inc. 3002 Dow Ave., Ste. 212 Tustin, CA 92780 714-505-4010

Sample disposal Instructions: Dis-	(agicana)	Relinquished by: (cimphina)	Reinquished by/(signature)	11/1/	Relinquished by/(signature)	1 3-+8	136-20	156-15	86-10	86-5	25 1/2	100	7, 30	84-60	67, 40	24 - 12		80-00		ールトング	Sample ID	Client: 47-30 MM Address: 47-30 MM Phone: 619-668-900 Project Manager: 15-1084	いって
Disposal @ \$2.00 each	Date / Hille		/Dafe / Time	11/21/17	Date / Time	× 25%	10015	1040	/0 30	1025	100	11/01/07 \$55	4 /430	1415	1405	1900	/300	1370			Date/Samplec Time	mos homes;	
Return to dient	Received by: (signature)		Received by: (signature)	En Land	Heck Ked by (signature)					W. 9									1000	11.360	Sample Container	19-665 9101	
Pickup	Date / Time			047 730	Date / Time																3260 3260 + OXY 3260 BTEX, OXY only 3270 3021 BTEX 3015M (gasoline)	Date: // Project Name Collector: Batch # 17	
	Turn ground time:	Received good conditions 48	Seals Intect? Y/N/NA	Chain of Custody seals Y/N/NA	Total # of containers					\ \ \		XX			_	XX	1	-	+		3015M (diesel) 3015M Ext./Carbon Chain 5010/7000 Title 22 Metals 3260 (TPH-M/BTEX/F Total Lead (Pb)	0120	
		(r	bbranea (a cc)		5		1141 32	72	47	is mora.	1914/162	23	ir Hold	2 (Hald .	20/10/1	(4)	41	(2)	16 11018	7	aboratory ID #	Client Project #: COC 71370)
		1	high con	• •		1.		‡	-	+		_	~	1	~	<u></u>	-				Fotal # of containers	· [3] [

SunStar Laboratories, Inc. 3002 Dow Ave., Ste. 212 Tustin, CA 92780 714-505-4010

Chain of Custody Record

Relinquished by: (signature) Relinquished by: (signature) Relinquished by: (signature)	87 - 18 87 - 18	男ナール Sample ID	Client: FF-2 Address: 4730 / A Phone: 019-66 5: Project Manager: Back
Date / Time Page 1 Date / Time Page 1 Date / Time Page 2 00 arch	1 1 1/2 1/2 S	Date/Sampled Time	1905 Fax: 61
Received by: (signature) Heceived by: (signature) Heceived by: (signature)		Sample Container Type Type	213
Date / Time Date / Time		8260 8260 + OXY 8260 8TEX, OXY only 8270 8021 BTEX 8015M (gasoline)	Date://_Project Name:
Total # of containers Chain of Custody seals Y/N/NA Seals intact? Y/N/NA Received good condition/cold Received from times:	X	8015M (diesel) 8015M Ext./Carbon Chain 6010/7000 Title 22 Metals ×8260 (TPH-M/BTEX/M × Total/Lead (Ph)	1701522 1701522
848	31 Hold	CO	
email result to		Comments/Preservative	Page: 3 of 3 Client Project # COL - 705//3- 2 COC 71372
0.4 101e	**************************************		I (

